



# AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

LOCAL 4 • LOCAL 11 • LOCAL 18 • LOCAL 32

## AMFA-SWA **OSG** SYSTEM BOARD AGENDA

January 12, 2022

CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4324	GROUP	ALL	D184165 (R/H HORIZONTAL STAB HAS LIGHTNING STRIKE DAMAGE, OTBD TRAILING EDGE AFT CORNER MOD ON AIRCRAFT: 7820. <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	JH
OSG-4393	GROUP	ALL	727-61-02 (FNC - Spoiler Ratio Changer No-Back Assembly) ON AIRCRAFT: 7831. <i>CURRENTLY ON COMPANY HOLD</i>	DL
OSG-4460	GROUP	ALL	725-RCB-35-01 (RAI - Remove and Install Armed Door Slide Warning Straps) ON AIRCRAFT: 969, 757, 239, 7833, 770, 776, 778, 8600, 421, 915, 445, 8311, 8672, 8619.	DL
OSG-4461	GROUP	ALL	752-200-00-03 (Health Check - Door Warning System - Sensors/Switches) ON AIRCRAFT: 969, 757, 7833, 8600, 915, 445, 8311, and 8672.	DL
OSG-4462	GROUP	ALL	728-22-21 (DVI - Out-of-Tank Wire Bundle (Installed on Fuel Tank)) ON AIRCRAFT: 969, 8600, 421, and 8311.	DL
OSG-4463	GROUP	ALL	732-305-00-01 (REP – Steering System Cables for the Nose Gear) ON AIRCRAFT: 239, 770, 776, 778, and 8311.	DL
OSG-4464	GROUP	ALL	757-645-000-01 (DVI - External - Left Upper Wing Panel) ON AIRCRAFT: 757.	DL
OSG-4465	GROUP	ALL	757-645-000-02 (DVI - External - Left Upper Wing Panel) ON AIRCRAFT: 757.	DL
OSG-4466	GROUP	ALL	727-61-02 (FNC - Spoiler Ratio Changer No-Back Assembly) ON AIRCRAFT: 7833, 445, and 8672.	DL
OSG-4467	GROUP	ALL	27-41-81-JIC (27-41-81-JIC) ON AIRCRAFT: 778, and 915.	DL



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
<b>OSG-4468</b>	<b>GROUP</b>	<b>ALL</b>	727-108-00-02 (REM – Stabilizer Jackscrew Assembly) ON AIRCRAFT: 778, 915, and 8672.	<b>DL</b>
<b>OSG-4469</b>	<b>GROUP</b>	<b>ALL</b>	727-108-00-03 (INST – Stabilizer Jackscrew Assembly) ON AIRCRAFT: 778, 915, and 8672.	<b>DL</b>
<b>OSG-4470</b>	<b>GROUP</b>	<b>ALL</b>	727-41-04 (AD - DVI - Stabilizer Trim Ballscrew, Ballnut, Return Tubes and Upper and Lower Gimbal Pins) ON AIRCRAFT: 915, and 8672.	<b>DL</b>
<b>OSG-4471</b>	<b>GROUP</b>	<b>ALL</b>	727-41-05 (AD - DVI - Stabilizer Trim Ballscrew, Ballnut, Return Tubes and Upper and Lower Gimbal Pins) ON AIRCRAFT: 915, and 8672.	<b>DL</b>
<b>OSG-4472</b>	<b>GROUP</b>	<b>ALL</b>	757-644-000-01 (SDI - Left Lower Wing Panel Under Flap Track Fittings (Direction 1 and Direction 2) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4473</b>	<b>GROUP</b>	<b>ALL</b>	757-644-000-02 (SDI - Right Lower Wing Panel Under Flap Track Fittings (Direction 1 and Direction 2)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4474</b>	<b>GROUP</b>	<b>ALL</b>	757-644-001-01 (SDI - Left Lower Wing Panel Under Flap Track Fittings (Direction 1)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4475</b>	<b>GROUP</b>	<b>ALL</b>	757-644-001-02 (SDI - Right Lower Wing Panel Under Flap Track Fittings (Direction 1)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4476</b>	<b>GROUP</b>	<b>ALL</b>	757-638-000-01 (SDI - External - Left Rear Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4477</b>	<b>GROUP</b>	<b>ALL</b>	757-638-000-02 (SDI - External - Left Rear Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4478</b>	<b>GROUP</b>	<b>ALL</b>	757-632-010-01 (SDI - External - Left Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4479</b>	<b>GROUP</b>	<b>ALL</b>	757-632-010-02 (SDI - External - Right Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4480</b>	<b>GROUP</b>	<b>ALL</b>	757-622-000-01 (SDI - External - Left Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
<b>OSG-4481</b>	<b>GROUP</b>	<b>ALL</b>	757-622-000-02 (SDI - External - Right Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4482</b>	<b>GROUP</b>	<b>ALL</b>	757-619-101-01 (SDI (LFEC) - External - Left Lower Wing Panel, Splice Stringers)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4483</b>	<b>GROUP</b>	<b>ALL</b>	757-619-101-02 (SDI (LFEC) - External - Right Lower Wing Panel, Splice Stringers)) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4484</b>	<b>GROUP</b>	<b>ALL</b>	757-607-100-01 (SDI - Wing Center Section Left Lower Panel) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4485</b>	<b>GROUP</b>	<b>ALL</b>	757-607-100-02 (SDI - Wing Center Section Right Lower Panel) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4486</b>	<b>GROUP</b>	<b>ALL</b>	757-606-000-01 (SDI - Wing Center Section Left Lower Panel) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4487</b>	<b>GROUP</b>	<b>ALL</b>	757-606-000-02 (SDI - Wing Center Section Right Lower Panel) ON AIRCRAFT: 770, 421, 776, and 778.	<b>DL</b>
<b>OSG-4488</b>	<b>GROUP</b>	<b>ALL</b>	725-RCB-35-01 (RAI - Remove and Install Armed Door Slide Warning Straps) ON AIRCRAFT: 409, 968, 7836, 562, 236, 451, 7862, 461, 7722, 231, 7817, 784, 914, 8309, 8674, 7863, 7814, 908, 455, 462, and 456	<b>DL</b>
<b>OSG-4489</b>	<b>GROUP</b>	<b>ALL</b>	752-200-00-03 (Health Check - Door Warning System - Sensors/Switches) ON AIRCRAFT: 968, 7836, 562, 451, 461, 914, 8309, 8674, 908, 455, 462, and 456.	<b>DL</b>
<b>OSG-4490</b>	<b>GROUP</b>	<b>ALL</b>	732-305-00-01 (REP – Steering System Cables for the Nose Gear) ON AIRCRAFT: 409, 236, 7862, 7722, 231, 7817, 784, 8309, 8674, 7836, and 7814.	<b>DL</b>
<b>OSG-4491</b>	<b>GROUP</b>	<b>ALL</b>	727-61-02 (FNC - Spoiler Ratio Changer No-Back Assembly) ON AIRCRAFT: 7836, 451, 461, 8674, 455, 462, and 456.	<b>DL</b>
<b>OSG-4492</b>	<b>GROUP</b>	<b>ALL</b>	728-22-21 (DVI - Out-of-Tank Wire Bundle (Installed on Fuel Tank) ON AIRCRAFT: 968, 7862, 7817, 8309, 7863 and 7814.	<b>DL</b>



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4493	GROUP	ALL	727-41-05 (AD - LUB - Stabilizer Trim Actuator and Actuator Gimbal Pins) ON AIRCRAFT: 461, 231, 784, 914, and 8674.	DL
OSG-4494	GROUP	ALL	727-41-04 (AD - DVI - Stabilizer Trim Ballscrew, Ballnut, Return Tubes and Upper and Lower Gimbal Pins) ON AIRCRAFT: 7722, 231, 784, 914, and 8674.	DL
OSG-4495	GROUP	ALL	27-41-81-JIC (27-41-81-JIC) ON AIRCRAFT: 7722, 231, 784, and 914.	DL
OSG-4496	GROUP	ALL	727-108-00-02 (REM – Stabilizer Jackscrew Assembly) ON AIRCRAFT: 7722, 231, 784, 914, and 8674.	DL
OSG-4498	GROUP	ALL	727-108-00-03 (INST – Stabilizer Jackscrew Assembly) ON AIRCRAFT: 7722, 231, 784, 914, and 8674.	DL
OSG-4499	GROUP	ALL	QM-20-153-00409 (737NG - SWA - NDT INSPECTION - POST REPAIR INSPECTIONS OF BS 540 CHORD AT S-22R) ON AIRCRAFT: 409, 231, and 462.	DL
OSG-4501	GROUP	ALL	725-60-10 (INSP - Emergency Equipment - Flight Deck) ON AIRCRAFT: 462.	WD
OSG-4502	GROUP	ALL	725-60-11 (INSP - Emergency Equipment - Cabin) ON AIRCRAFT: 462.	WD
OSG-4503	GROUP	ALL	5500-I-12302-NG (Repair Survey for LH Elevator Tab) ON AIRCRAFT: 455.	SP
OSG-4504	GROUP	ALL	7834-I-12141-NG (Thrust Reverser - Corrosion Inspection and Protection of T/R Isolation Valve (CVM) Connectors and Wire Harnesses) ON AIRCRAFT: 461.	CH
OSG-4505	GROUP	ALL	757-644-000-01 (SDI - Left Lower Wing Panel Under Flap Track Fittings (Direction 1 and Direction 2) ON AIRCRAFT: 409, 562, and 784.	DL
OSG-4507	GROUP	ALL	757-644-000-02 (SDI - Right Lower Wing Panel Under Flap Track Fittings (Direction 1 and Direction 2)) ON AIRCRAFT: 409, 562, and 784.	DL



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
<b>OSG-4508</b>	<b>GROUP</b>	<b>ALL</b>	757-644-001-01 (SDI - Left Lower Wing Panel Under Flap Track Fittings (Direction 1)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4509</b>	<b>GROUP</b>	<b>ALL</b>	757-644-001-02 (SDI - Right Lower Wing Panel Under Flap Track Fittings (Direction 1)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4510</b>	<b>GROUP</b>	<b>ALL</b>	757-638-000-01 (SDI - External - Left Rear Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, 7862 and 784.	<b>DL</b>
<b>OSG-4511</b>	<b>GROUP</b>	<b>ALL</b>	757-638-000-02 (SDI - External - Right Rear Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, 7862 and 784.	<b>DL</b>
<b>OSG-4512</b>	<b>GROUP</b>	<b>ALL</b>	757-632-010-01 (SDI - External - Left Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4513</b>	<b>GROUP</b>	<b>ALL</b>	757-632-010-02 (SDI - External - Right Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4514</b>	<b>GROUP</b>	<b>ALL</b>	757-622-000-01 (SDI - External - Left Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4515</b>	<b>GROUP</b>	<b>ALL</b>	757-622-000-02 (SDI - External - Right Front Spar Lower Chord (Skin Flange Inspections)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4516</b>	<b>GROUP</b>	<b>ALL</b>	757-619-101-01 (SDI (LFEC) - External - Left Lower Wing Panel, Splice Stringers)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4517</b>	<b>GROUP</b>	<b>ALL</b>	757-619-101-02 (SDI (LFEC) - External - Right Lower Wing Panel, Splice Stringers)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4518</b>	<b>GROUP</b>	<b>ALL</b>	757-607-100-01 (SDI - Wing Center Section Left Lower Panel)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4519</b>	<b>GROUP</b>	<b>ALL</b>	757-607-100-02 (SDI - Wing Center Section Right Lower Panel)) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>
<b>OSG-4520</b>	<b>GROUP</b>	<b>ALL</b>	757-606-000-01 (SDI - Wing Center Section Left Lower Panel) ON AIRCRAFT: 409, 562, and 784.	<b>DL</b>



## AMFA-SWA **OSG** System Board Agenda

**January 12, 2022**

Page 6 of 6

CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4521	GROUP	ALL	757-606-000-02 (SDI - Wing Center Section Right Lower Panel) ON AIRCRAFT: 409, 562, and 784.	DL