



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

LOCAL 4 • LOCAL 11 • LOCAL 18 • LOCAL 32

AMFA-SWA **OSG** SYSTEM BOARD AGENDA

March 10, 2021

CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3809	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550036, 003388, 0550037, 003371, 0550037, 002890 ON AC 7852 AND 431 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3810	GROUP	ALL	8757-660-000-01 MOD TYPE: 8 NBR: 757-660-000-01 REV: POS: 1 DVI - INT - TRACK #1 & #8 - OUTBOARD MAIN FLAP OUTBOARD TRACK INSPECT THE OUTBOARD MAIN FLAP, OUTBOARD TRACK AT WBL 357.7 PER DTR 57- 53-01-1A COMPONENT DISCREPANCY RECORD: 0570176 S-1827 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3811	GROUP	ALL	8757-660-000-01 MOD TYPE: 8 NBR: 757-660-000-01 REV: POS: 8 DVI - INT - TRACK #1 & #8 - OUTBOARD MAIN FLAP OUTBOARD TRACK INSPECT THE OUTBOARD MAIN FLAP, OUTBOARD TRACK AT WBL 357.7 PER DTR 57- 53-01-1A COMPONENT DISCREPANCY RECORD: 0570177 S-1826 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3812	GROUP	ALL	8757-662-000-01 MOD TYPE: 8 NBR: 757-662-000-01 REV: POS: 7 DVI - INT - TRACK #2 & #7 - OUTBOARD MAIN FLAP, INBOARD TRACK INSPECT THE OUTBOARD MAIN FLAP, INBOARD TRACK AT WBL 254.0 PER DTR 57- 53-03-1A COMPONENT DISCREPANCY RECORD: 0570172 S-2911 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3813	GROUP	ALL	8757-662-000-01 MOD TYPE: 8 NBR: 757-662-000-01 REV: POS: 2 DVI - INT - TRACK #2 & #7 - OUTBOARD MAIN FLAP, INBOARD TRACK INSPECT THE OUTBOARD MAIN FLAP, INBOARD TRACK AT WBL 254.0 PER DTR 57- 53-03-1A COMPONENT DISCREPANCY RECORD: 0570180 CF5174 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3814	GROUP	ALL	8757-664-000-01 MOD TYPE: 8 NBR: 757-664-000-01 REV: POS: 3 DVI - INT - TRACK #3 & #6 - INBOARD MAIN FLAP, OUTBOARD TRACK INSPECT THE INBOARD MAIN FLAP, OUTBOARD TRACK AT WBL 164.0 PER DTR 57- 53-06-1A COMPONENT DISCREPANCY RECORD: 0570178 S-2893 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3815	GROUP	ALL	8757-664-000-01 MOD TYPE: 8 NBR: 757-664-000-01 REV: POS: 6 DVI - INT - TRACK #3 & #6 - INBOARD MAIN FLAP, OUTBOARD TRACK INSPECT THE INBOARD MAIN FLAP, OUTBOARD TRACK AT WBL 164.0 PER DTR 57- 53-06-1A COMPONENT DISCREPANCY RECORD: 0570179 S-2919 ON AC 7852 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3817	GROUP	ALL	8757-667-000-01 MOD TYPE: 8 NBR: 757-667-000-01 REV: POS: 4 INTERNAL - DVI - INBOARD MAIN FLAP, INBOARD TRACK COMPONENT DISCREPANCY RECORD: 0570167 0493, 0570168 0491 ON AC 431 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3858	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550038 000827 0550039 000826 ON AC 7851 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	CH



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3859	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550038 000827 0550039 000826 ON AC 7851 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3860	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550037 7851#1 ON AC 7851 <i>CURRENTLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3904	GROUP	ALL	8755-647-000-01 MOD TYPE: 8 NBR: 755-647-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR HINGE FITTINGS 1 THROUGH 8 COMPONENT DISCREPANCY RECORD: 0550038 000878 ON AC 7813 <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3905	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550038 000878 ON AC 7813 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3906	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550038 000878 ON AC 7813 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3941	GROUP	ALL	8755-647-000-01 MOD TYPE: 8 NBR: 755-647-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR HINGE FITTINGS 1 THROUGH 8 COMPONENTS ON AC 550 DISCREPANCY RECORD: 0550038, 000350, 0550039, 000349, and AC 7812 DISCREPANCY RECORD: 0550038, 000848, 0550039, 000844 <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3942	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT ON AC 550 DISCREPANCY RECORD 0550039, 000349, 0550038, 000350 AND AC 7812 DISCREPANCY RECORD: 0550038, 000848, 0550039, 000844 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3943	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT ON AC 550 DISCREPANCY RECORD 0550039, 000349, 0550038, 000350 AND AC 7812 DISCREPANCY RECORD 0550038, 000848, 0550039, 000844 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3944	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT ON AC 550 DISCREPANCY RECORD: 0550036, 002555, 0550037, 002571, AC 7812 DISCREPANCY RECORD 0550036, 001953, 0550037, 001909 AND AC 563 DISCREPANCY RECORD 0550037 AND 002802 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3945	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT ON AC 550 DISCREPANCY RECORD: 0550039, 000349, 0550038, 000350 AND AC 7812 DISCREPANCY RECORD: 0550039 AND 000844 <i>CURRENTLY ON UNION HOLD</i>	Withdrawn W/O Prej
OSG-3946	GROUP	ALL	8757-688-000-01 MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 6 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT ON AC 7812 DISCREPANCY RECORD: 0570118 001987 AND AC 563 DISCREPANCY RECORD: 0570119 004251 <i>CURRENTLY ON UNION HOLD</i>	CH
OSG-3951	GROUP	ALL	OUTSOURCE OF SLIDING WINDOW ON 12/22/2020	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3952	GROUP	ALL	8727-61-02 MOD TYPE: 8 NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY, on Aircraft: 434.	DL
OSG-3953	GROUP	ALL	I14090 04 MOD TYPE: I NBR: 14090 REV: 04 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN on Aircraft: 434, 274, 729	DL
OSG-3954	GROUP	ALL	J725-RCB-35-01 RAI - REMOVE AND INSTALL ARMED DOOR SLIDE WARNING STRAPS, on Aircraft: 434, 200, 274.	DL
OSG-3955	GROUP	ALL	J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR, on Aircraft: 434, 200, 274, 211, 729, 7715.	DL
OSG-3956	GROUP	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES on Aircraft 434, 274.	DL
OSG-3957	GROUP	ALL	8727-108-00-02 MOD TYPE: 8 NBR: 727-108-00-02 REV: POS: REM - STABILIZER JACKSCREW ASSEMBLY on Aircraft: 729 and 274.	DL
OSG-3958	GROUP	ALL	8727-108-00-03 MOD TYPE: 8 NBR: 727-108-00-03 REV: POS: INST - STABILIZER JACKSCREW ASSEMBLY on Aircraft 274, and 729.	DL
OSG-3959	GROUP	ALL	8727-41-04 MOD TYPE: 8 NBR: 727-41-04 REV: POS: DVI - STABILIZER TRIM BALLSCREW, BALLNUT, RETURN TUBES AND UPPER AND LOWER GIMBAL PINS on Aircraft: 274 and 729.	DL
OSG-3961	GROUP	ALL	8727-41-05 MOD TYPE: 8 NBR: 727-41-05 REV: POS: LUB - STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS on Aircraft: 274, and 729.	DL
OSG-3962	GROUP	ALL	J11503177 SI#:0270200 DESC: JACKSCREW STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-10 MSN: BP07795 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, on Aircraft: 274.	DL
OSG-3963	GROUP	ALL	8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK), on Aircraft: 211.	DL
OSG-3964	GROUP	ALL	8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK), on Aircraft: 211.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3965	GROUP	ALL	OUTSOURCE OF SLIDING WINDOW ON 12/28/2020	DL
OSG-3966	GROUP	ALL	OUTSOURCE OF SLIDING WINDOW ON 1/6/2021	DL
OSG-3967	GROUP	ALL	8727-61-02 MOD TYPE: 8 NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO- BACK ASSEMBLY on aircraft: 565; 564; 7724; 439; 567; 566.	DL
OSG-3968	GROUP	ALL	I14090 04 MOD TYPE: I NBR: 14090 REV: 04 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN, ON AIRCRAFT: 565; 406; 564; 7724; 7855; 7848; 439; 567; 566; 276; 272.	DL
OSG-3969	GROUP	ALL	J J725-RCB-35-01 RAI - REMOVE AND INSTALL ARMED DOOR SLIDE WARNING STRAPS, ON AIRCRAFT: 565; 401; 406; 564; 7724; 7855; 275; 439; 567; 566; 276; 272.	DL
OSG-3970	GROUP	ALL	J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR, ON AIRCRAFT: 565; 401; 406; 564; 7724; 7855; 275; 439; 567; 566; 276; 272.	DL
OSG-3971	GROUP	ALL	8727-108-00-02 MOD TYPE: 8 NBR: 727-108-00-02 REV: POS: REM - STABILIZER JACKSCREW	DL
OSG-3972	GROUP	ALL	8727-108-00-03 MOD TYPE: 8 NBR: 727-108-00-03 REV: POS: INST - STABILIZER JACKSCREW ASSEMBLY, ON AIRCRAFT: 401; 275; 439; 272 AND 276.	DL
OSG-3973	GROUP	ALL	8727-41-04 MOD TYPE: 8 NBR: 727-41-04 REV: POS: DVI - STABILIZER TRIM BALLSCREW, BALLNUT, RETURN TUBES AND UPPER AND LOWER GIMBAL PINS, ON AIRCRAFT: 401; 275; 439; 272; AND 276.	DL
OSG-3974	GROUP	ALL	8727-41-05 MOD TYPE: 8 NBR: 727-41-05 REV: POS: LUB - STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS, ON AIRCRAFT: 401; 275; 439; 272; AND 276.	DL
OSG-3975	GROUP	ALL	8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK), ON AIRCRAFT: 401; AND 406	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3976	GROUP	ALL	8757-688-000-01MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 7 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT DISCREPANCY RECORD: 0570119 000774, ON AIRCRAFT: 7848.	CH
OSG-3977	GROUP	ALL	J11586730 SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-11 MSN: BP08133 POS: P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, ON AIRCRAFT: 401.	DL
OSG-3978	GROUP	ALL	J11563662 SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-10 MSN: BP07920 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, ON AIRCRAFT: 275	DL
OSG-3979	GROUP	ALL	J11565687 SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-6 MSN:KE00660 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, ON AIRCRAFT 439.	DL
OSG-3980	GROUP	ALL	J11566201 SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-6 MSN:KE00303 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, ON AIRCRAFT: 276.	DL
OSG-3981	GROUP	ALL	J11563680 SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-6 MSN:KE00693 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01, ON AIRCRAFT: 272.	DL
OSG-3982	GROUP	ALL	Q1-A53-22766 03 MOD TYPE: Q NBR: 1-A53-22766 REV: 03 POS: 737NG - SWA - OTHER - INSPECTION (NDT) - BS 540, S-22R, POST REPAIR INSPECTION (SB 737-53-1294), ON AIRCRAFT: 406.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3983	GROUP	ALL	8757-688-000-01 MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 6 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT DISCREPANCY RECORD: 0570118 001545, ON AIRCRAFT: 564.	CH
OSG-3984	GROUP	ALL	8757-688-000-01MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 7 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT DISCREPANCY RECORD: 0570119 001530, ON AIRCRAFT: 564.	CH
OSG-3985	GROUP	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHEES ON AIRCRAFT: 272; 275; 276; 439; 564; 566; AND 567.	DL
OSG-3986	GROUP	ALL	I12038 02MOD TYPE: I NBR: 12038 REV: 02 POS: FLIGHT DECK LH #1 WINDOW FRAME BONDED DOUBLER - POSTINSTALLATION HFEC INSPECTION, ON AIRCRAFT 566.	Withdraw W/O Prej
OSG-3987	GROUP	ALL	I12040 02MOD TYPE: I NBR: 12040 REV: 02 POS: FLIGHT DECK RH #1 WINDOW FRAME BONDED DOUBLER POSTINSTALLATION HFEC INSPECTION, ON AIRCRAFT 566.	Withdraw W/O Prej
OSG-3988	GROUP	ALL	8755-647-000-01 MOD TYPE: 8 NBR: 755-647-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR HINGE FITTINGS 1 THROUGH 8 COMPONENT DISCREPANCY RECORD: 0550038 000384 ON AIRCRAFT 565.	Withdraw W/O Prej
OSG-3989	GROUP	ALL	8755-647-000-01 MOD TYPE: 8 NBR: 755-647-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR HINGE FITTINGS 1 THROUGH 8 COMPONENT DISCREPANCY RECORD: 0550039 000385 ON AIRCRAFT 565.	Withdraw W/O Prej
OSG-3990	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550038 000384 ON AIRCRAFT 565.	CH
OSG-3991	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550039 000385 ON AIRCRAFT 565.	CH



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-3992	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550038 000384 ON AIRCRAFT 565.	CH
OSG-3993	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550039 000385 ON AIRCRAFT 565.	CH
OSG-3994	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550036 001684 ON AIRCRAFT 565.	CH
OSG-3995	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550037 002073 ON AIRCRAFT 565.	CH
OSG-3996	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550038 000384 ON AIRCRAFT 565.	Withdrawn W/O Prej
OSG-3997	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550039 000385 ON AIRCRAFT 565.	Withdrawn W/O Prej
OSG-3998	GROUP	ALL	8757-606-000-01 MOD TYPE: 8 NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL ON AIRCRAFT 406.	DL
OSG-3999	GROUP	ALL	8757-606-000-02 MOD TYPE: 8 NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL ON AIRCRAFT 406.	DL
OSG-4000	GROUP	ALL	8757-607-100-01 MOD TYPE: 8 NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL ON AIRCRAFT 406.	DL
OSG-4001	GROUP	ALL	8757-607-100-02 MOD TYPE: 8 NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL ON AIRCRAFT 406.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4002	GROUP	ALL	8757-619-101-01 MOD TYPE: 8 NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS ON AIRCRAFT 406.	DL
OSG-4003	GROUP	ALL	8757-619-101-02 MOD TYPE: 8 NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS ON AIRCRAFT 406.	DL
OSG-4004	GROUP	ALL	8757-620-101-01 MOD TYPE: 8 NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER ON AIRCRAFT 406.	DL
OSG-4005	GROUP	ALL	8757-620-101-02 MOD TYPE: 8 NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER ON AIRCRAFT 406.	DL
OSG-4006	GROUP	ALL	8757-622-000-01 MOD TYPE: 8 NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4007	GROUP	ALL	8757-622-000-02 MOD TYPE: 8 NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4008	GROUP	ALL	8757-632-010-01 MOD TYPE: 8 NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4009	GROUP	ALL	8757-632-010-02 MOD TYPE: 8 NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4010	GROUP	ALL	8757-638-000-01 MOD TYPE: 8 NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4011	GROUP	ALL	8757-638-000-02 MOD TYPE: 8 NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) ON AIRCRAFT 406.	DL
OSG-4012	GROUP	ALL	8757-644-000-01 MOD TYPE: 8 NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) ON AIRCRAFT 406.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4013	GROUP	ALL	8757-644-000-02 MOD TYPE: 8 NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) ON AIRCRAFT 406.	DL
OSG-4014	GROUP	ALL	8757-644-001-01 MOD TYPE: 8 NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) ON AIRCRAFT 406.	DL
OSG-4015	GROUP	ALL	8757-644-001-02 MOD TYPE: 8 NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) ON AIRCRAFT 406.	DL
OSG-4016	GROUP	ALL	8757-688-000-01 MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 7 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT DISCREPANCY RECORD: 0570119 001806, ON AIRCRAFT: 7855.	CH
OSG-4017	GROUP	ALL	8757-688-000-01 MOD TYPE: 8 NBR: 757-688-000-01 REV: POS: 6 DVI - INTERNAL - INBOARD SPOILER HINGE/ACTUATOR FITTINGS COMPONENT DISCREPANCY RECORD: 0570118 002297, ON AIRCRAFT: 7848.	CH
OSG-4018	GROUP	ALL	OUTSOURCE OF SLIDING WINDOW ON 1/13/2021	DL
OSG-4019	GROUP	ALL	I14090 04 MOD TYPE: I NBR: 14090 REV: 04 POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN, ON AIRCRAFT: 279; 558; 733; 7748; and 7816	DL
OSG-4020	GROUP	ALL	J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR on aircraft: 279; 404; 405; 558; 733; 935; 955; 7748; and 7816.	DL
OSG-4021	GROUP	ALL	J725-RCB-35-01 RAI - REMOVE AND INSTALL ARMED DOOR SLIDE WARNING STRAPS, on aircraft: 279; 404; 935; 955; 7748; and 7816.	DL
OSG-4022	GROUP	ALL	8727-108-00-02 MOD TYPE: 8 NBR: 727-108-00-02 REV: POS: REM - STABILIZER JACKSCREW ASSEMBLY on aircraft: 279, 404, and 733.	DL
OSG-4023	GROUP	ALL	8727-108-00-03 MOD TYPE: 8 NBR: 727-108-00-03 REV: POS: INST - STABILIZER JACKSCREW ASSEMBLY on aircraft: 279, 404, and 733.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4024	GROUP	ALL	8727-41-04 MOD TYPE: 8 NBR: 727-41-04 REV: POS: DVI - STABILIZER TRIM BALLSCREW, BALLNUT, RETURN TUBES AND UPPER AND LOWER GIMBAL PINS, on aircraft: 279; 404; and 733.	DL
OSG-4025	GROUP	ALL	8727-41-05 MOD TYPE: 8 NBR: 727-41-05 REV: POS: LUB - STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS on aircraft: 279, 404; 733	DL
OSG-4026	GROUP	ALL	E14571 01 MOD TYPE: E NBR: 14571 REV: 01 POS: LH AUTOMATIC OVERWING EXIT (AOE) DOOR SURROUND STRUCTURE - UPPER DOOR SILL FILLET SEAL on aircraft 733.	CH
OSG-4027	GROUP	ALL	E16448 01 MOD TYPE: E NBR: 16448 REV: 01 POS: RH AUTOMATIC OVERWING EXIT (AOE) DOOR SURROUND STRUCTURE - UPPER DOOR SILL FILLET SEAL on aircraft 733.	CH
OSG-4028	GROUP	ALL	SI#: 0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-10 MSN: BP07412 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01 on aircraft 733.	DL
OSG-4029	GROUP	ALL	8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) on aircraft: 404; 405; 558; and 955.	DL
OSG-4030	GROUP	ALL	SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-6 MSN:KE00790 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01 on aircraft 404.	DL
OSG-4031	GROUP	ALL	SI#:0270200 DESC: JACKSCRE STAB JACKSCREW (700 ONLY) REMOVE AND REPLACE THE FOLLOWING COMPONENT: MPN:251A4510-6 MSN: KE00813 POS:P OTHER POSSIBLE POSITIONS: REASON FOR REMOVAL: LIFE LIMITED 01 on aircraft 279.	DL
OSG-4034	GROUP	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES on aircraft: 279; 733; 955; 7748; and 7816.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4035	GROUP	ALL	MOD TYPE: I NBR: 15029 REV: 01 POS: 2 STABILIZERS - HORIZONTAL STABILIZER LOWER SKIN - INSPECTION OF SKIN PANEL OUTBOARD OF SB 737-55-1096 COMPONENT DISCREPANCY RECORD: 0550045 000816 on aircraft 404.	RB
OSG-4036	GROUP	ALL	MOD TYPE: I NBR: 15029 REV: 01 POS: 1 STABILIZERS - HORIZONTAL STABILIZER LOWER SKIN - INSPECTION OF SKIN PANEL OUTBOARD OF SB 737-55-1096 COMPONENT DISCREPANCY RECORD: 0550046 000816 on aircraft 404.	RB
OSG-4037	GROUP	ALL	8727-61-02 MOD TYPE: 8 NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO- BACK ASSEMBLY on aircraft 935.	DL
OSG-4038	GROUP	ALL	J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES on aircraft 935.	DL
OSG-4041	GROUP	ALL	8757-606-000-01 MOD TYPE: 8 NBR: 757-606-000- 01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL on aircraft 405.	DL
OSG-4042	GROUP	ALL	8757-606-000-02 MOD TYPE: 8 NBR: 757-606-000- 02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL on aircraft 405.	DL
OSG-4043	GROUP	ALL	8757-607-100-01 MOD TYPE: 8 NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL on aircraft 405.	DL
OSG-4044	GROUP	ALL	8757-607-100-02 MOD TYPE: 8 NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL on aircraft 405.	DL
OSG-4045	GROUP	ALL	8757-619-101-01 MOD TYPE: 8 NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS on aircraft 405.	DL
OSG-4046	GROUP	ALL	8757-619-101-02 MOD TYPE: 8 NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS on aircraft 405.	DL
OSG-4047	GROUP	ALL	8757-620-101-01 MOD TYPE: 8 NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER on aircraft 405.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4048	GROUP	ALL	8757-620-101-02 MOD TYPE: 8 NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER on aircraft 405.	DL
OSG-4049	GROUP	ALL	8757-622-000-01 MOD TYPE: 8 NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4050	GROUP	ALL	8757-622-000-02 MOD TYPE: 8 NBR: 757-622-000- 02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4051	GROUP	ALL	8757-632-010-01 MOD TYPE: 8 NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4052	GROUP	ALL	8757-632-010-02 MOD TYPE: 8 NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4053	GROUP	ALL	8757-638-000-01 MOD TYPE: 8 NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4054	GROUP	ALL	8757-638-000-02 MOD TYPE: 8 NBR: 757-638-000- 02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 405.	DL
OSG-4055	GROUP	ALL	8757-644-000-01 MOD TYPE: 8 NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) on aircraft 405.	DL
OSG-4056	GROUP	ALL	8757-644-000-02 MOD TYPE: 8 NBR: 757-644-000- 02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) on aircraft 405.	DL
OSG-4057	GROUP	ALL	8757-644-001-01 MOD TYPE: 8 NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) on aircraft 405.	DL
OSG-4058	GROUP	ALL	8757-644-001-02 MOD TYPE: 8 NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) on aircraft 405.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4059	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550038 001135 on aircraft 7816.	CH
OSG-4060	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: P SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550039 001110 on aircraft 7816.	CH
OSG-4061	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550038 001135 on aircraft 7816.	CH
OSG-4062	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: P GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550039 001110 on aircraft 7816.	CH
OSG-4063	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550036 001326 on aircraft 7816.	CH
OSG-4064	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550037 001399 on aircraft 7816.	CH
OSG-4065	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550038 001135 on aircraft 7816.	Withdrawn W/O Prej
OSG-4066	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: P SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550039 001110 on aircraft 7816.	Withdrawn W/O Prej
OSG-4067	GROUP	ALL	8757-606-000-01 MOD TYPE: 8 NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL on aircraft 404.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4068	GROUP	ALL	8757-606-000-02 MOD TYPE: 8 NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL on aircraft 404.	DL
OSG-4069	GROUP	ALL	8757-619-101-01 MOD TYPE: 8 NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS on aircraft 404.	DL
OSG-4070	GROUP	ALL	8757-619-101-02 MOD TYPE: 8 NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS on aircraft 404.	DL
OSG-4071	GROUP	ALL	8757-620-101-01 MOD TYPE: 8 NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER on aircraft 404.	DL
OSG-4072	GROUP	ALL	8757-620-101-02 MOD TYPE: 8 NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER on aircraft 404.	DL
OSG-4073	GROUP	ALL	8757-622-000-01 MOD TYPE: 8 NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4074	GROUP	ALL	8757-622-000-02 MOD TYPE: 8 NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4075	GROUP	ALL	8757-632-010-01 MOD TYPE: 8 NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4076	GROUP	ALL	8757-632-010-02 MOD TYPE: 8 NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4077	GROUP	ALL	8757-638-000-01 MOD TYPE: 8 NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4078	GROUP	ALL	8757-638-000-02 MOD TYPE: 8 NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) on aircraft 404.	DL
OSG-4079	GROUP	ALL	8757-644-000-01 MOD TYPE: 8 NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) on aircraft 404.	DL



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4080	GROUP	ALL	8757-644-000-02 MOD TYPE: 8 NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) on aircraft 404.	DL
OSG-4081	GROUP	ALL	8757-644-001-02 MOD TYPE: 8 NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) on aircraft 404.	DL
OSG-4082	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: LH SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550038 001221 on aircraft 271.	CH
OSG-4083	GROUP	ALL	8755-648-000-01 MOD TYPE: 8 NBR: 755-648-000-01 REV: POS: RH SDI (HFEC) - INTERNAL - ELEVATOR MAST ARM ASSEMBLY (ELEVATOR ACTUATOR FITTING) COMPONENT DISCREPANCY RECORD: 0550039 001217 on aircraft 271.	CH
OSG-4084	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: LH GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550038 001221 on aircraft 271.	CH
OSG-4085	GROUP	ALL	8755-649-000-01 MOD TYPE: 8 NBR: 755-649-000-01 REV: POS: RH GVI - INTERNAL - ELEVATOR HORN BALANCE WEIGHT SUPPORT STRUCTURE COMPONENT DISCREPANCY RECORD: 0550039 001217 on aircraft 271.	CH
OSG-4086	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: LH SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550036 2458 on aircraft 271.	CH
OSG-4087	GROUP	ALL	8755-652-000-01 MOD TYPE: 8 NBR: 755-652-000-01 REV: POS: RH SDI (HFEC) - INTERNAL - 183A8700 HINGE/MAST ARM FITTING UPPER FLANGE COMPONENT DISCREPANCY RECORD: 0550037 002449 on aircraft 271.	CH
OSG-4088	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: LH SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550038 001221 on aircraft 271.	Withdrawn W/O Prej



CASE #	GRIEVANT	STA	NATURE	DECISION
OSG-4089	GROUP	ALL	8755-657-000-01 MOD TYPE: 8 NBR: 755-657-000-01 REV: POS: RH SDI (HFEC) - INTERNAL - 183A1400 - BRACKET ASSY - TAB CONTROL MECHANISM, ELEVATOR COMPONENT DISCREPANCY RECORD: 0550039 001217 on aircraft 271.	Withdrawn W/O Prej