



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 1 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-4729	GROUP PMX	DAL	BLENDED WORK <i>PREVIOUSLY ON JOINT HOLD</i> <i>PREVIOUSLY ON UNION HOLD</i> <i>CURRENTLY ON COMPANY HOLD</i>	SETTLED PRIOR
SWA-4739	GROUP PMX	DAL	BLENDED WORK <i>PREVIOUSLY ON JOINT HOLD</i> <i>PREVIOUSLY ON UNION HOLD</i> <i>CURRENTLY ON COMPANY HOLD</i>	SETTLED PRIOR
SWA-4756	GROUP GSE	OAK	VENDOR ACCOMPLISHING COVERED WORK <i>PREVIOUSLY ON COMPANY HOLD</i> <i>PREVIOUSLY ON UNION HOLD</i> <i>CURRENTLY ON JOINT HOLD</i>	DEADLOCKED
SWA-4838	GROUP	ALL	INTENT TO CONTRACT OUT ETOPS <i>PREVIOUSLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	JOINT HOLD
SWA-4859	JEREMY WORD	MCO	ABOLISHMENT OF 4 LEAD POSITIONS IN MCO <i>PREVIOUSLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-4918	GROUP	ALL	OUTSOURCING VIOLATION LEFT STAB RIB GUSSET CRACK <i>PREVIOUSLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-4941	GROUP	ALL	IMPROPER BID PROCEDURES <i>PREVIOUSLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-4942	GROUP PLANT MX	PHX	OUTSOURCING CUSTOMARY WORK <i>PREVIOUSLY ON UNION HOLD</i> <i>CURRENTLY ON JOINT HOLD</i>	SETTLED PRIOR
SWA-4951	JEREMY WORD	MCO	NOT ALLOWED TO BUMP PER CONTRACT AFTER SLOT ABOLISHED <i>PREVIOUSLY ON COMPANY HOLD</i> <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 2 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-4978	CHRIS OCONNOR	DEN	IMPROPER APPLICATION OF ATTENDANCE POLICY <i>CURRENTLY ON UNION HOLD</i>	REMANDED BACK
SWA-4980	ERIC WATTS	BWI	OVERTIME BYPASS <i>CURRENTLY ON UNION HOLD</i>	JOINT HOLD
SWA-5066	GROUP APP TECH	DAL	IMPROPER FACT-FINDING PROCEDURES <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5067	GROUP	ALL	DOWN LINE BYPASS FOR A/C N953 DAMAGED DURING TOW FOR RTS GEG <i>CURRENTLY ON UNION HOLD</i>	DEADLOCKED
SWA-5070	LARRY DILDINE	DAL	CROSS UTILIZATION OF THE INSPECTION WORKGROUP <i>CURRENTLY ON UNION HOLD</i>	JOINT HOLD
SWA-5072	GROUP APP TECH	DAL	DISCIPLINE TIMELINE VIOLATION <i>CURRENTLY ON COMPANY HOLD</i>	DEADLOCKED
SWA-5118	GROUP GSE	DAL	OUTSOURCING VIOLATION (TUG WIRE HARNESES) <i>CURRENTLY ON UNION HOLD</i>	COMPANY HOLD
SWA-5119	GROUP GSE	DAL	CROSSUTILIZATION VIOLATION (REFURB SHOP DOING GSE SHOP WORK) <i>CURRENTLY ON UNION HOLD</i>	COMPANY HOLD
SWA-5120	GROUP GSE	DAL	CROSSUTILIZATION VIOLATION (BWI STATION ACCOMPLISHING REFURB SHOP WORK) <i>CURRENTLY ON UNION HOLD</i>	COMPANY HOLD
SWA-5127	FRED BISHOP	PHX	IMPROPER DENIAL FOR BUMP UP LEAD	COMPANY HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 3 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5128	TOM STEPHENSON	PHX	IMPROPER DENIAL FOR BUMP UP LEAD	COMPANY HOLD
SWA-5129	ROB SKIBINSKI	LAS	KNOWN RII TASK ON RON & INSPECTION BYPASS	DEADLOCKED
SWA-5131	GROUP DAY SHOPS	PHX	SPECIAL INSPECTION ACCOMPLISHED BY A VENDOR AT SEATAC	DEADLOCKED
SWA-5132	RUI LEONARDO	LAS	RAMP MANAGEMENT DISPATCHING 2 A/C WITH KNOWN CARGO DAMAGE ON LINERS	DEADLOCKED
SWA-5134	GROUP AMT	DAL	BLENDED WORK VIOLATION - GE BOROSCOPE	WITHDRAWN
SWA-5135	TONY GLASOE	DAL	DOWNLINE VIOLATION - KNOWN RII	UNION HOLD
SWA-5136	GROUP AMT	DAL	IMPROPER DISCIPLINARY POLICY – NON-COMPLIANCE	DEADLOCKED
SWA-5137	GROUP AMT	DAL	SUSPENSION OF DAY TRADE PRIVILEGES	DEADLOCKED
SWA-5139	JESSE TARANGO	DAL	CROSS UTILIZATION VIOLATION - EVENING LINE PERFORMING RON WORK	WITHDRAWN
SWA-5140	GROUP AMT	DAL	OUTSOURCING VIOLATION - ESCAPE SLIDES	UNION HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 4 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5141	GROUP	ALL	NBR: 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5142	GROUP	ALL	NBR: 14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5143	GROUP	ALL	NBR: 12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5144	GROUP	ALL	NBR: 14090 REV: POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED
SWA-5145	GROUP	ALL	J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES	DEADLOCKED
SWA-5146	GROUP	ALL	NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY	DEADLOCKED
SWA-5147	GROUP	ALL	NBR: 08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES	JOINT HOLD
SWA-5148	GROUP	ALL	NBR: 12235 REV: 08 POS: DOOR WARNING SYSTEM - SENSOR/SWITCH HEALTH CHECK	DEADLOCKED
SWA-5149	GROUP	ALL	G408493 L/H ENGINE HAS ONE LOOSE OUTER LIP SKIN FASTENER ON THE TRAILING EDGE OF SEGMENT #2 AT THE SPLICE AREA OF SEGMENT #1 AND SEGMENT #2.	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 5 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5150	GROUP	ALL	NBR: 28418 REV: POS: BS 540 LOWER BULKHEAD CHORD(LEFTSIDE)INDICATES CRACKAT THE FWD HOLE 3 FASTENERS BELOW STR.22L	DEADLOCKED
SWA-5151	GROUP	ALL	NBR: 12002 REV: 03 POS: 1 WINGS - L/H INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION COMPONENT DISCREPANCY RECORD: 0270307 T1185	SETTLED PRIOR
SWA-5152	GROUP	ALL	5741-E-14084 LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5153	GROUP	ALL	INSP-21EO-03374 HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5154	GROUP	ALL	INSP-52EO-03312 DOOR WARNING SYSTEM - SENSOR/SWITCH HEALTH CHECK	DEADLOCKED
SWA-5155	GROUP	ALL	INSP-25EA-04249 CARGO COMPARTMENT LINER INSPECTION	UNION HOLD
SWA-5156	GROUP	ALL	MOD-25EO-01310 737-800 OWWE WINDOW SHADE MODIFICATION	DEADLOCKED
SWA-5157	GROUP	ALL	MOD-30EO-03548 ICE AND RAIN PROTECTION – PITOT AND STATIC – POLARITY STANDARDIZATION TO ADDRESS	DEADLOCKED
SWA-5158	GROUP	ALL	INSP-12EO-10310 FLIGHT CONTROLS - AILERON BALANCE TAB HINGE BEARING AND ROD END BEARINGS	WITHDRAWN



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 6 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5159	GROUP	ALL	REPAIR-54EA-03637 OF BLIND FASTENERS INSTALLED ON INLET COWL W/O# 261821	DEADLOCKED
SWA-5160	GROUP	ALL	INSP-54EA-03636 COMPONENT - SWA - NACELLE - TLD TRACKING FOR GVI OF BLIND FASTENERS INSTALLED ON INLET COWL P/N 314-2100-3 S/N 8109001 (CURRENTLY ON A/C 8601)	WITHDRAWN
SWA-5161	GROUP	ALL	REPAIR-54EA-03639 COMPONENT- SWA-NACELLE-TLD TRACKING FOR PERMANENT REPAIR OGF BLIND FASTENERS INSTALLED ON INLET COWL P/N 314-2100-3, S/N 8108001. AC 8603	DEADLOCKED
SWA-5162	GROUP	ALL	752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES W/O#261821	DEADLOCKED
SWA-5163	GROUP	ALL	NBR: 757-605-010-01 REV: POS: SDI - EXTERNAL - WING CENTER SECTION LEFT SIDE OF BODY SPLICE, LOWER SURFACE SKIN	DEADLOCKED
SWA-5164	GROUP	ALL	NBR: 757-605-010-02 REV: POS: SDI - EXTERNAL - WING CENTER SECTION RIGHT SIDE OF BODY SPLICE, LOWER SURFACE SKIN	DEADLOCKED
SWA-5165	GROUP	ALL	NBR: 757-605-020-01 REV: POS: SDI - EXTERNAL - WING CENTER SECTION LEFT SIDE OF BODY SPLICE, LOWER SURFACE SKIN	DEADLOCKED
SWA-5166	GROUP	ALL	NBR: 757-605-020-02 REV: POS: SDI - EXTERNAL - WING CENTER SECTION RIGHT SIDE OF BODY SPLICE, LOWER SURFACE SKIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 7 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5167	GROUP	ALL	NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5168	GROUP	ALL	NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5169	GROUP	ALL	NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5170	GROUP	ALL	NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5171	GROUP	ALL	NBR: 757-609-000-01 REV: POS: SDI - INTERNAL - LEFT SIDE OF BODY SPLICE UPPER AND LOWER FRONT SPAR	DEADLOCKED
SW5172	GROUP	ALL	NBR: 757-609-000-02 REV: POS: SDI - INTERNAL - RIGHT SIDE OF BODY SPLICE UPPER AND LOWER FRONT SPAR	DEADLOCKED
SWA-5173	GROUP	ALL	NBR: 757-614-110-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING SKIN PANEL	DEADLOCKED
SWA-5174	GROUP	ALL	NBR: 757-614-110-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING SKIN PANEL	DEADLOCKED
SWA-5175	GROUP	ALL	NBR: 757-614-130-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5176	GROUP	ALL	NBR: 757-614-130-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING PANEL SKIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 8 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5177	GROUP	ALL	NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5178	GROUP	ALL	NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5179	GROUP	ALL	NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5180	GROUP	ALL	NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5181	GROUP APP TECH	DAL	GRIEVANCE PROCEDURE VIOLATION	DEADLOCKED
SWA-5182	GENE PAINTER	DAL	UNJUST DISCIPLINE - TRAINING NON-COMPLIANCE	DEADLOCKED
SWA-5183	GROUP	ALL	NBR: 757-623-000-01 REV: POS: DVI - INTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5184	GROUP	ALL	NBR: 757-623-000-02 REV: POS: DVI - INTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5185	GROUP	ALL	NBR: 757-625-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 9 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5186	GROUP	ALL	NBR: 757-625-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5187	GROUP	ALL	NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5188	GROUP	ALL	NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5189	GROUP	ALL	NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5190	GROUP	ALL	NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5191	GROUP	ALL	NBR: 757-641-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5192	GROUP	ALL	NBR: 757-641-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5193	GROUP	ALL	NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5194	GROUP	ALL	NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 10 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5195	GROUP	ALL	NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5196	GROUP	ALL	NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5197	GROUP	ALL	NBR: 732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5198	GROUP	ALL	NBR: 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5199	GROUP	ALL	NBR: 12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5200	GROUP	ALL	NBR: 14150 REV: POS: FWD CARGO DOOR HANDLE INSPECTION FOR GOUGING & MISSING STUD CAP COMPONENT DISCREPANCY RECORD: 0520046 000065	AWARDED IN PART
SWA-5201	GROUP	ALL	NBR: 14150 REV: POS: AFT CARGO DOOR HANDLE INSPECTION FOR GOUGING & MISSING STUD CAP COMPONENT DISCREPANCY RECORD: 0520047 000065	AWARDED IN PART
SWA-5202	GROUP	ALL	J757-265-01-01 LEFT MAIN LANDING GEAR BEAM HANGAR LINK FREE PLAY CHECK	SETTLED PRIOR



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION


AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 11 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5203	GROUP	ALL	J757-265-02-01 RIGHT MAIN LANDING GEAR BEAM HANGER LINK FREE PLAY CHECK	SETTLED PRIOR
SWA-5204	GROUP	ALL	14150 FWD CARGO DOOR HANDLE INSPECTION FOR GOUGING & MISSING STUD CAP	WITHDRAWN
SWA-5205	GROUP	ALL	14150 AFT CARGO DOOR HANDLE INSPECTION FOR GOUGING & MISSING STUD CAP	WITHDRAWN
SWA-5206	GROUP	ALL	NBR: 14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5207	GROUP	ALL	NBR: 14090 REV: POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED
SWA-5208	GROUP	ALL	G455865 CABIN FLOOR INTERCOSTAL LOCATED BELOW THE FWD. ENTRY DOOR WALKWAY LOCATED AT BS.312 TO BS.328 HAS A FASTENER THAT IS NOT PROPERLY FASTENED DUE TO MISSING NUT PLATE.	WITHDRAWN
SWA-5209	GROUP	ALL	G455868 CABIN FLOOR INTERCOSTAL FRAME LOCATED BELOW THE FWD. LAVATORY FLOOR AT BS.294 TO BS.312 HAS A FASTENER THAT IS NOT PROPERLY FASTENED DUE TO MISSING NUT PLATE	WITHDRAWN
SWA-5210	GROUP	ALL	NBR: 08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES	JOINT HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 12 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5211	GROUP	ALL	NBR: 12235 REV: 08 POS: DOOR WARNING SYSTEM - SENSOR/SWITCH HEALTH CHECK	DEADLOCKED
SWA-5212	GROUP	ALL	NBR: 36803 REV: POS: FOUND A CRACK INDICATION AT STA 539.5 AT SECOND FASTENER HOLE DOWN FROM STRINGER 22R PER HFEC HOLE PROBE NDT PART 6 51-00-00 PROC.23 (MARKED CRACKS ON FWD AND AFT SIDE OF HOLE IN SKIN)	DEADLOCKED
SWA-5213	GROUP	ALL	NBR: 36805 REV: POS: FOUND A CRACK INDICATION AT STA 539.5 AT SECOND FASTENER HOLE DOWN FROM STRINGER 22L PER HFEC HOLE PROBE NDT PART 6 51-00-00 PROC.23 (MARKED CRACKS ON FWD AND AFT SIDE OF HOLE IN SKIN)	DEADLOCKED
SWA-5214	GROUP	ALL	NBR: 757-643-100-01 REV: POS: SDI - (UT) - LEFT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	DEADLOCKED
SWA-5215	GROUP	ALL	NBR: 757-643-100-02 REV: POS: SDI - (UT) - RIGHT SKIN AT NACELLE SUPPOT FITTING ATTACHMENTS	DEADLOCKED
SWA-5216	GROUP	ALL	NBR: 757-643-101-01 REV: POS: SDI (HFEC) - LEFT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	DEADLOCKED
SWA-5217	GROUP	ALL	NBR: 757-643-101-02 REV: POS: SDI (HFEC) - RIGHT SKIN AT NACELLE SUPPORT FITTING ATTACHMENTS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 13 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5218	GROUP	ALL	MOD 7 151342 AFT CARGO SCUFF PLATE DENTS PERMENENT REPAIR	UNION HOLD
SWA-5219	GROUP	ALL	NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5220	GROUP	ALL	NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5221	GROUP	ALL	NBR: 757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5222	GROUP	ALL	NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5223	GROUP	ALL	NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5224	GROUP	ALL	NBR: 757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS	DEADLOCKED
SWA-5225	GROUP	ALL	NBR: 757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS	DEADLOCKED
SWA-5226	GROUP	ALL	NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED
SWA-5227	GROUP	ALL	NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 14 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5228	GROUP	ALL	NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5229	GROUP	ALL	NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5230	GROUP	ALL	NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5231	GROUP	ALL	NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5232	GROUP	ALL	NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5233	GROUP	ALL	NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5234	GROUP	ALL	NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5235	GROUP	ALL	NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5236	GROUP	ALL	NBR: 757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 15 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5237	GROUP	ALL	NBR: 757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5238	GROUP	ALL	NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5239	GROUP	ALL	NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5240	GROUP	ALL	NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5241	GROUP	ALL	NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5242	GROUP	ALL	NBR: 757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5243	GROUP	ALL	NBR: 757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5244	GROUP	ALL	NBR: 757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5245	GROUP	ALL	NBR: 757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 16 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5246	GROUP	ALL	NBR: 757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5247	GROUP	ALL	NBR: 757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5248	GROUP	ALL	NBR: 757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5249	GROUP	ALL	NBR: 757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5250	GROUP	ALL	NBR: 757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5251	GROUP	ALL	NBR: 757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5252	GROUP	ALL	NBR: 757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5253	GROUP	ALL	NBR: 757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 17 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5254	GROUP	ALL	NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5255	GROUP	ALL	NBR: 757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5256	GROUP	ALL	NBR: 757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	WITHDRAWN
SWA-5257	GROUP	ALL	NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	WITHDRAWN
SWA-5258	GROUP	ALL	NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	WITHDRAWN
SWA-5259	GROUP	ALL	NBR: 757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS	WITHDRAWN
SWA-5260	GROUP	ALL	NBR: 757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS	WITHDRAWN
SWA-5261	GROUP	ALL	NBR: 757-614-130-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING PANEL SKIN	WITHDRAWN
SWA-5262	GROUP	ALL	NBR: 757-614-130-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING PANEL SKIN	WITHDRAWN
SWA-5263	GROUP	ALL	NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS	WITHDRAWN



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 18 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5264	GROUP	ALL	NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS	WITHDRAWN
SWA-5265	GROUP	ALL	NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	WITHDRAWN
SWA-5266	GROUP	ALL	NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5267	GROUP	ALL	NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA5268	GROUP	ALL	NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5269	GROUP	ALL	NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5270	GROUP	ALL	NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5271	GROUP	ALL	NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED
SWA-5272	GROUP	ALL	NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 19 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5273	GROUP	ALL	NBR: 757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5274	GROUP	ALL	NBR: 757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS	DEADLOCKED
SWA-5275	GROUP	ALL	NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5276	GROUP	ALL	NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2)	DEADLOCKED
SWA-5277	GROUP	ALL	NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5278	GROUP	ALL	NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1)	DEADLOCKED
SWA-5279	GROUP	ALL	NBR: 757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5280	GROUP	ALL	NBR: 757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL STRINGERS	DEADLOCKED
SWA-5281	GROUP	ALL	NBR: 757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 20 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5182	GROUP	ALL	NBR: 757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1)	DEADLOCKED
SWA-5183	GROUP	ALL	NBR: 757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5284	GROUP	ALL	NBR: 757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FASTENER ATTACHMENTS	DEADLOCKED
SWA-5285	GROUP	ALL	NBR: 757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5286	GROUP	ALL	NBR: 757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	DEADLOCKED
SWA-5287	GROUP	ALL	NBR: 757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27	WITHDRAWN
SWA-5288	GROUP	ALL	NBR: 757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED
SWA-5289	GROUP	ALL	NBR: 757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS (DIRECTION 1)	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 21 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5290	GROUP	ALL	NBR: 757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5291	GROUP	ALL	NBR: 757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS	DEADLOCKED
SWA-5292	AARON HANSEN	SMF	VENDOR PERFORMED WORK WITHOUT CALLING O/T	UNION HOLD
SWA-5293	TONY GLASOE	DAL	INSPECTION BACKFILL VIOLATION	DEADLOCKED
SWA-5294	GROUP AMT	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-5295	DAN BURGESS	MDW	GRIEVANCE PROCEEDURE	JOINT HOLD
SWA-5296	DAN BURGESS	MDW	DOWNLINE VIOLATION A/C 755 AT INDY	SETTLED PRIOR
SWA-5297	GROUP AMT	DAL	IDLING OF HEAVY MAINTENANCE LINE	DEADLOCKED
SWA-5298	DOBBS/LARSEN	LAS	VENDOR ACCOMPLISHED 8 DAY CHECK & MELS	DEADLOCKED
SWA-5299	GROUP AMT	DAL	OUTSOURCING VIOLATION – 4 TH LINE	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 22 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5300	CAREY PAGAN	DAL	OVERTIME BYPASS – SLIDE SHOP	WITHDRAWN
SWA-5301	KEITH YOUNG	DAL	OVERTIME BYPASS – SLIDE SHOP	WITHDRAWN
SWA-5303	CHRIS LEIDAH	BWI	DOWNLINE VIOLATION	COMPANY HOLD
SWA-5304	MARK YOUNG	BWI	LMS TRAINING DISCIPLINE	DEADLOCKED
SWA-5305	STEVE PRETTO	MDW	LEAD PREP	REMANDED BACK
SWA-5306	LOUIS UPCHURCH	MDW	SUPERVISOR PERFORMING COVERED WORK	DEADLOCKED
SWA-5307	GROUP ALL	MDW	DOWNLINE PROCEDURE	DEADLOCKED
SWA-5308	JOEY STRAZZANTE	TPA	GROUND OPS USING TAIL STAND TO SUPPORT AIRCRAFT	UNION HOLD
SWA-5309	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS.	UNION HOLD
SWA-5310	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS.	UNION HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 23 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5311	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS.	UNION HOLD
SWA-5312	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS.	UNION HOLD
SWA-5313	GROUP ALL	ALL	OUTSOURCED MV CHECK AND ASSOCIATED TASKS.	UNION HOLD
SWA-5314	GROUP HRON AMT/INSPECTOR	PHX	OUTSOURCE A/C N487 NOSE GEAR CORROSION	COMPANY HOLD
SWA-5315	AKI OSHIRO	PHX	CONTRACT MX ACCOMPLISHED AN MV2 A/C N217 THAT WAS NOT DUE	COMPANY HOLD
SWA-5316	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5317	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5318	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5319	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5320	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 24 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5321	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5322	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5323	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5324	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5325	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5326	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5327	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5328	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5329	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5330	GROUP INSP	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 25 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5331	GROUP AMT	DAL	IDLING OF HEAVY MX LINE	DEADLOCKED
SWA-5332	GROUP AMT	ALL	AC 934 DOUBLE ENGINE CHANGE AT MCI	COMPANY HOLD
SWA-5333	GROUP AMT	ALL	NBR: 732-21-04 REV: POS: RST - STEERING SYSTEM CABLES FOR THE NOSE GEAR	DEADLOCKED
SWA-5334	GROUP AMT	ALL	NBR: 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS	DEADLOCKED
SWA-5335	GROUP AMT	ALL	NBR: 14084 REV: 03 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE	DEADLOCKED
SWA-5336	GROUP AMT	ALL	NBR: 12246 REV: 01 POS: HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION	DEADLOCKED
SWA-5337	GROUP AMT	ALL	NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO- BACK ASSEMBLY	DEADLOCKED
SWA-5338	GROUP AMT	ALL	NBR: 12235 REV: 08 POS: DOOR WARNING SYSTEM - SENSOR/SWITCH HEALTH CHECK	DEADLOCKED
SWA-5339	GROUP AMT	ALL	NBR: 14090 REV: POS: INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 26 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5340	GROUP AMT	ALL	NBR: 14150 REV: POS: FWD CARGO DOOR HANDLE INSPECTION FOR GOUGING & MISSING STUD CAP COMPONENT DISCREPANCY RECORD: 0520046 002603	AWARDED IN PART
SWA-5341	GROUP AMT	ALL	NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5342	GROUP AMT	ALL	NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER	DEADLOCKED
SWA-5343	GROUP AMT	ALL	NBR: 08913 REV: 07 POS: INSTALLATION OF MAGEE PLASTICS RETURN AIR GRILLES	JOINT HOLD
SWA-5344	GROUP AMT	ALL	NBR: 28564 REV: POS: DURING SI # 12043-53, FOUND SKIN CRACK INDICATION, BS 540, BELOW STRINGER 22R, SECOND FASTENER FROM THETOP IN THE AFT ROW	DEADLOCKED
SWA-5345	GROUP AMT	ALL	D287037 FOUND PULL RIVETS ON #1 ENG NOSE INLET COWL (3 EACH) @ 10 O'CLOCK POSITION	DEADLOCKED
SWA-5346	GROUP AMT	ALL	D287038 FOUND PULL RIVETS ON #2 ENG NOSE INLET COWL (2 EACH) @ 10' O'CLOCK POSITION.	DEADLOCKED
SWA-5347	GROUP AMT	ALL	NBR: 28565 REV: POS: DURING SI # 12043-53, FOUND SKIN CRACK INDICATION, BS 540, BELOW STRINGER 22R, SECOND FASTENER FROM THETOP IN THE AFT ROW.	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 27 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5348	GROUP AMT	ALL	J757-265-01-01 LEFT MAIN LANDING GEAR BEAM HANGAR LINK FREE PLAY CHECK J757-265-02-01 RIGHT MAIN LANDING GEAR BEAM HANGER LINK FREE PLAY CHECK	SETTLED PRIOR
SWA-5349	GROUP AMT	ALL	J757-265-02-01 RIGHT MAIN LANDING GEAR BEAM HANGER LINK FREE PLAY CHECK	SETTLED PRIOR
SWA-5350	GROUP AMT	ALL	NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5351	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	COMPANY HOLD
SWA-5352	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5353	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1)	DEADLOCKED
SWA-5354	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL	DEADLOCKED
SWA-5355	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL	DEADLOCKED
SWA-5356	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS	DEADLOCKED



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 • AMFA Local 11 • AMFA Local 18 • AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 28 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5357	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS	DEADLOCKED
SWA-5358	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-614-130-01 REV: POS: GVI - EXTERNAL - LEFT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5359	GROUP AMT	ALL	MOD TYPE: 8 NBR: 757-614-130-02 REV: POS: GVI - EXTERNAL - RIGHT LOWER WING PANEL SKIN	DEADLOCKED
SWA-5360	GROUP AMT	ALL	MULTIPLE FAN BLADE LUBE AND INSPECTIONS	DEADLOCKED
SWA-5361	TERRY ARNOLD	MDW	DOWNLINE VIOLATION	DEADLOCKED
SWA-5362	CHRIS LEIDAHN	BWI	DOWNLINE VIOLATION	REMANDED BACK
SWA-5363	ALLEN DOORNBOS	MDW	COMPANY NOT REPLACING WORN RAIN GEAR	SETTLED PRIOR
SWA-5364	PATRICK AMORE	MDW	COMPANY ADDING STRESS IN WORKPLACE	REMANDED BACK
SWA-5365	LOUIS UPCHURCH	MDW	BID LOCATION VIOLATION	REMANDED BACK
SWA-5366	CRAIG CARLO	BWI	OVERTIME AWARD AFTER CALLOUT	SETTLED PRIOR



AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

AMFA Local 4 · AMFA Local 11 · AMFA Local 18 · AMFA Local 32

SWA-AMFA SYSTEM BOARD AGENDA

MAY 9, 2018

Page: 29 of 29

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5367	PAT SPLAN	MDW	DOWNLINE VIOLATION	REMANDED BACK

5/14/2018 8:49 AM