



# AIRCRAFT MECHANICS FRATERNAL ASSOCIATION

LOCAL 4 • LOCAL 11 • LOCAL 18 • LOCAL 32

## AMFA-SWA SYSTEM BOARD AGENDA

May 15, 2019

CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-5904	GROUP AMT	DAL	OUTSOURCING VIOLATION THRUST REVERSER ASSEMBLY	Settled Prior
SWA-5905	GROUP AMT	DAL	OUTSOURCING VIOLATION CUSTOMARY COMPOSITE SHOP WORK INCLUDING AFT FLAP	Settled Prior
SWA-5906	GROUP AMT	DAL	OUTSOURCING VIOLATION WINGLET FROM COMPOSITE SHOP	Settled Prior
SWA-5907	GROUP AMT	DAL	CROSS-UTILIZATION VIOLATION	Settled Prior
SWA-5999	GROUP	ALL	GROUP AMT / AMT /G481253 WHILE PERFORMING EA1-A55-3553 FOUND THREE DENTS ON R H HORIZONTAL STAB. A/C 203	Deadlocked
SWA-6012	KEITH WRIGHT	HOU	LATE OT CALLOUT RESULTS IN TEMP VACANCY NOT BEING FILLED BY LEAD AMT <i>PREVIOUSLY ON UNION HOLD PREVIOUSLY ON JOINT HOLD CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6080	GROUP	ALL	GROUP AMT / AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 930 <i>PREVIOUSLY ON COMPANY HOLD PREVIOUSLY ON JOINT HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6088	NINO DIMAGGIO	DAL	BLENDED WORK VIOLATION – GE ON-WING <i>PREVIOUSLY ON COMPANY HOLD PREVIOUSLY ON JOINT HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6100	NINO DIMAGGIO	DAL	<p>BLEDED WORK VIOLATION – GE ON-WING</p> <p><i>PREVIOUSLY ON COMPANY HOLD</i></p> <p><i>PREVIOUSLY ON JOINT HOLD</i></p> <p><i>CURRENTLY ON UNION HOLD</i></p>	UNION HOLD
SWA-6101	GROUP	MDW	<p>MDW MANAGEMENT REQUIRE CHANGES TO BADGING</p> <p><i>PREVIOUSLY ON COMPANY HOLD</i></p> <p><i>PREVIOUSLY ON UNION HOLD</i></p> <p><i>CURRENTLY ON UNION HOLD</i></p>	JOINT HOLD
SWA-6115	GROUP	ALL	<p>AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 727</p> <p><i>PREVIOUSLY ON COMPANY HOLD</i></p> <p><i>CURRENTLY ON UNION HOLD</i></p>	UNION HOLD
SWA-6159	GROUP	ALL	<p>FAILING TO CONSISTENTLY RECOGNIZE AND APPLY PRIOR SYSTEM BOARD RULINGS AS FINAL AND BINDING.</p>	DEADLOCKED
SWA-6161	TONI BUI	PHX	<p>APP TECH / CALLED FOR EXTERIOR OT, AFTER FINISHING EXTERIOR WAS MOVED TO HANGAR RON.</p>	REMANDED BACK
SWA-6165	CHRIS MARTIN	MCO	<p>UNJUST PUNISHMENT OF CLAIMED NO CALL NO SHOW</p>	REMANDED BACK
SWA-6178	GROUP	ALL	<p>AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 729, 935</p> <p><i>PREVIOUSLY ON COMPANY HOLD</i></p> <p><i>CURRENTLY ON UNION HOLD</i></p>	UNION HOLD
SWA-6224	NINO DIMAGGIO	DAL	<p>COMPANY FAILURE TO ADHERE TO SETTLEMENT AGREEMENT RE SWA-3930</p> <p><i>PREVIOUSLY ON JOINT HOLD</i></p> <p><i>CURRENTLY ON COMPANY HOLD</i></p>	COMPANY HOLD
SWA-6225	GROUP ALL	DAL	<p>DENIAL OF VACATION AND FLOATING HOLIDAY REQUESTS</p>	DEADLOCKED
SWA-6232	ROGER EVETT	DAL	<p>OVERTIME CALLOUT VIOLATION</p>	WITHDRAWN



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6233	GROUP PMX	DAL	REQUEST TO ADD TOOL TO INDEX <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6234	RICK HAMMACK	DAL	DOWNLINE VIOLATION – AC 714 @ SAN	WITHDRAWN
SWA-6235	GROUP ALL	DAL	SICK TIME USAGE – DOCTORS NOTE REQUIREMENT	DEADLOCKED
SWA-6236	GROUP ALL	DAL	DENIAL OF DAY TRADE PRIVILEGES	DEADLOCKED
SWA-6237	GROUP ALL	DAL	RESTRICTION OF DAY TRADE PRIVILEGES	DEADLOCKED
SWA-6238	GROUP ALL	DAL	NEGOTIATION VIOLATION RE LOA #1 <i>PREVIOUSLY ON UNION HOLD CURRENTLY ON JOINT HOLD</i>	JOINT HOLD
SWA-6239	GROUP ALL	DAL	SICK TIME USGAE VIOLATION RE DOCTORS NOTE	DEADLOCKED
SWA-6240	GROUP ALL	DAL	DENIAL OF DAY TRADE PRIVILEGES	DEADLOCKED
SWA-6241	MATT TOWNSEND	DAL	DOWNLINE VIOLATION – AC 286 @ AMA <i>PREVIOUSLY ON UNION HOLD CURRENTLY ON JOINT HOLD</i>	JOINT HOLD
SWA-6242	GROUP AMT	DAL	OUTSOURCING VIOLATION – AC483 OTS FERRY TO VENDOR <i>PREVIOUSLY ON UNION HOLD CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6244	GROUP	MCO	DENIAL OF PROPERLY SUBMITTED DAY TRADE REQUESTS	DEADLOCKED
SWA-6245	LOUIS UPCHURCH	MDW	UNSAFE TRANSPORT OF OXYGEN CYLINDERS IN NEW COMPANY VEHICLES <i>PREVIOUSLY ON UNION HOLD CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6247	GROUP	HOU	DENIAL OF PROPERLY SUBMITTED DAY TRADE REQUESTS	DEADLOCKED
SWA-6248	GROUP	HOU	DENIAL OF PROPERLY SUBMITTED VACATION AND FLOATING HOLIDAY REQUESTS	DEADLOCKED
SWA-6249	JOSE BOTELLO	MCO	BID LOCATION REASSIGNMENT VIOLATION	DEADLOCKED
SWA-6250	GROUP	ALL	OUTSOURCE OF MV2'S	DEADLOCKED
SWA-6251	WALTER GIEBELHAUS	HOU	DENIAL OF PROPERLY REQUESTED F/H	DEADLOCKED
SWA-6252	SAM HERNANDEZ	MCO	IMPROPER CALLOUT DUE TO BID LOCATION REASSIGNMENT <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6253	GROUP ALL	MCO	DENIAL OF DAY TRADES MCO	DEADLOCKED
SWA-6254	BJ RITTER	HOU	DENIAL OF PROPERLY REQUESTED VAC/FH	DEADLOCKED
SWA-6255	THOMAS BECK	HOU	DENIAL OF PROPERLY REQUESTED DAY TRADES	DEADLOCKED
SWA-6256	THOMAS BECK	HOU	DENIAL OF PROPERLY REQUESTED VACATION AND FLOATING HOLIDAYS	DEADLOCKED
SWA-6257	GROUP ALL	ALL	OTS A/C OUTSOURCED LESS THAN 5 DAYS	DEADLOCKED
SWA-6258	ROBERT WOOSTER	DEN	OUTSOURCED GSE WORK <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6259	TROY LEON	PHX	DENIAL OF PROPERLY REQUESTED VACATION	DEADLOCKED
SWA-6260	GROUP	PHX,LAS	DENIAL OF DAY TRADES	DEADLOCKED
SWA-6261	GROUP	PHX,LAS	DENIAL OF VACATION, FLOATING HOLIDAY	DEADLOCKED
SWA-6262	JOHN DICIACCIO	LAX	DENIAL OF DAY TRADES	DEADLOCKED
SWA-6263	GROUP	LAS	DENIAL OF DAY TRADES	DEADLOCKED
SWA-6264	LISA INMON	PHX	REQUIRED TO PROVIDE DR. NOTE	DEADLOCKED
SWA-6267	GROUP ALL	DAL	UNILATERAL IMPLEMENTATION OF CROSS UTILIZATION	DEADLOCKED
SWA-6268	MATT TOWNSEND	DAL	OUTSOURCING VIOLATION – RON WORK	DEADLOCKED
SWA-6269	GROUP ALL	DAL	<p>BLENDED WORK VIOLATION – GE ON WING – AC 553</p> <p><i>PREVIOUSLY ON UNION HOLD</i></p> <p><i>CURRENTLY ON COMPANY HOLD</i></p>	COMPANY HOLD
SWA-6293	GROUP ALL	ALL	<p>GROUP/ AMT / THE FOLLOWING OTS AIRCRAFT WERE OUTSOURCED AND COMPLETED BY A THIRD PARTY WHICH IS A VIOLATION OF THE CBA. SEE AIRCRAFT LISTED, EACH WAS OTS UNDER FIVE DAYS.</p> <p>7818,285 AND 227</p>	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6294	GROUP ALL	ALL	THE FOLLOWING OTS AIRCRAFT WERE OUTSOURCED AND COMPLETED BY A THIRD PARTY WHICH IS A VIOLATION OF THE CBA. SEE AIRCRAFT LISTED, EACH WAS OTS UNDER FIVE DAYS 734 AND 7857	DEADLOCKED
SWA-6295	GROUP ALL	ALL	THE FOLLOWING OVERNIGHT INTERMEDIATE MAINTENANCE C CHECK EVENTS WERE SCHEDULED AND COMPLETED BY A THIRD PARTY VENDOR WHICH IS A VIOLATION OF THE CBA. SEE AIRCRAFT LISTED BELOW 7849,764,790,261,570,7711,288,7863,774	DEADLOCKED
SWA-6296	GROUP ALL	ALL	THE FOLLOWING OVERNIGHT INTERMEDIATE MAINTENANCE EVENTS WERE SCHEDULED AND COMPLETED BY A THIRD PARTY VENDOR WHICH IS A VIOLATION OF THE CBA. SEE AIRCRAFT LISTED BELOW 754,424,932,778,913,940,452,470,7841,7849, 8749,7881,7858,243,7733	DEADLOCKED
SWA-6297	GROUP ALL	ALL	THE FOLLOWING LONG WEEKEND INTERMEDIATE MAINTENANCE EVENT WAS SCHEDULED AND COMPLETED BY A THIRD PARTY VENDOR WHICH IS A VIOLATION OF THE CBA. AIRCRAFT 451	DEADLOCKED
SWA-6298	GROUP ALL	ALL	C CHECK OUTSOURCING 735,469,730,AND 570	DEADLOCKED
SWA-6299	GROUP ALL	ALL	OUTSOURCING VIOLATIONS 7835,706,AND 243	DEADLOCKED
SWA-6300	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 451	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6301	GROUP ALL	ALL	THE COMPANY IS OUTSOURCING WORK EXCLUSIVELY HERETOFORE PERFORMED BY THE BARGAINING UNIT. FLIGHT DECK SEAT ASSEMBLIES.	DEADLOCKED
SWA-6302	GROUP ALL	ALL	OUTSOURCING VIOLATIONS A/C 769, 288, 7711, 231, 298, 952, 474	DEADLOCKED
SWA-6303	GROUP ALL	ALL	OUTSOURCING VIOLATIONS A/C 410, 779	DEADLOCKED
SWA-6304	GROUP ALL	ALL	OUTSOURCING VIOLATIONS A/C 442, 7712, 219, 494, 277, 774, 7863	DEADLOCKED
SWA-6305	GROUP ALL	ALL	OUTSOURCING VIOLATIONS A/C 754, 284, 724, 963	DEADLOCKED
SWA-6306	GROUP ALL	ALL	DENIAL OF CANCELLATION REQUEST OF FLOATING HOLIDAYS	DEADLOCKED
SWA-6309	GROUP ALL	ALL	THE FOLLOWING OVERNIGHT INTERMEDIATE MAINTENANCE EVENTS WERE SCHEDULED AND COMPLETED BY A THIRD PARTY VENDOR WHICH IS A VIOLATION OF THE CBA. SEE AIRCRAFT LISTED BELOW 765,499,7849,469,7747,7856,476,246,AND 792	DEADLOCKED
SWA-6310	GROUP ALL	ALL	728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) AC 733 <i>PREVIOUSLY ON JOINT HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6329	GROUP ALL	ALL	GROUP / AMT / OUTSOURCING VIOLATIONS 553, 7841, 227, 465, 7873, 723, 904, 954, 225, 720, 7729, 790	DEADLOCKED
SWA-6330	GROUP ALL	ALL	GROUP / AMT / OUTSOURCING VIOLATIONS A/C 945,7727,7864 AND 7723	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6331	GROUP ALL	ALL	GROUP / AMT / OUTSOURCING VIOLATIONS OUTSOURCING VIOLATIONS A/C 292, 7825	DEADLOCKED
SWA-6332	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6333	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6334	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6335	CLARKE DICKERSON	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6336	CLARKE DICKERSON	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6337	CLARKE DICKERSON	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6338	CLARKE DICKERSON	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6339	CLARKE DICKERSON	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6340	RON JONAITIS	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6341	CHRIS REED	DAL	OUTSOURCING VIOLATION	DEADLOCKED
SWA-6342	TOM CARLE	DAL	OUTSOURCING VIOLATION	DEADLOCKED
SWA-6343	MATT TOWNSEND	DAL	OUTSOURCING VIOLATION	DEADLOCKED





<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6344	GROUP ALL	DAL	DENIAL OF DAY TRADES	DEADLOCKED
SWA-6345	GROUP ALL	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6346	GROUP ALL	DAL	DENIAL OF VACATION AND FLOATING HOLIDAYS	DEADLOCKED
SWA-6347	GROUP ALL	DAL	DOCTORS NOTE REQUIREMENT FOR ABSENCES DUE TO ILLNESS	DEADLOCKED
SWA-6348	GROUP ALL	DAL	DENIAL OF UNION BUSINESS TIME	DEADLOCKED
SWA-6349	SCOTT ANDREZWJSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6350	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6351	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6352	DANIEL CACCIA	DAL	DENIED FLOATING HOLIDAY	DEADLOCKED
SWA-6353	BRYAN WASHAUSEN	DAL	DENIED BEREAVEMENT LEAVE EXTENTION	DEADLOCKED
SWA-6356	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 946, 493, 8658, 8697, 912	DEADLOCKED
SWA-6357	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 792,251,231,442 AND 281	DEADLOCKED
SWA-6358	GROUP ALL	ALL	OUTSOURCING VIOLATION C CHECK A/C 7846, 415	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6359	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 8622, 8648, 218	DEADLOCKED
SWA-6360	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 8543, 7826, 8524, 8675	DEADLOCKED
SWA-6361	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 420	DEADLOCKED
SWA-6362	GROUP ALL	ALL	OUTSOURCING VIOLATION A/C 730, 908, 446, 233, 918, 7846	DEADLOCKED
SWA-6363	MESFIN CHAKA	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6364	MESFIN CHAKA	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6365	DOUG GILLASPY	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6366	DOUG GILLASPY	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6367	CHRIS REED	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6368	GREG DIBAGGIO	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6369	PERRY OTTO	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6370	MESFIN CHAKA	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6371	SECIL MATTHEW	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6372	GEOFFREY SNYDER	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6373	LEEROY DELAROSA	PHX	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6374	WES GRIFFIN	PHX	DENIED USE OF VACATION	DEADLOCKED
SWA-6375	SHANE FAULKNER	PHX	DAY TRADE APPROVALS NOT FOLLOWING PAST PRACTICE	DEADLOCKED
SWA-6376	JAMES ANDERSON	LAX	NOT CALLED FOR OT, OTHER STATION BROUGHT IN TO WORK OTS A/C <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON JOINT HOLD</i>	JOINT HOLD
SWA-6377	REMBER MEJIA	LAX	NOT CALLED FOR OT, OTHER STATION BROUGHT IN TO WORK OTS A/C <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON JOINT HOLD</i>	JOINT HOLD
SWA-6380	JACOB GRANATO	BWI	SUPERVISOR PERFORMING COVERED WORK WITH CONTRACT MX <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6381	CHRIS LEIDAHN	BWI	CONTRACT MX PERFORMED A MV-3 ON A/C 769 <i>PREVIOUSLY ON COMPANY HOLD CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6382	LANCE BEAUCHAMP	MCO	UNJUST/WRONGFUL DISCIPLINE <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6383	SHANE WATTERS	HOU	UNJUST/WRONGFUL DISCIPLINE	REMANDED BACK
SWA-6384	ISREAL GARCIA	HOU	UNJUST/WRONGFUL DISCIPLINE	REMANDED BACK



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6385	GARY FISHMAN	MCO	UNJUST LOI RECEIVED	WITHDRAWN
SWA-6386	PAUL WEBER	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6387	RICHARD PERRY	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6388	HARRY RIVERA	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6389	DOUG GILLASPY	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6390	LYNDON HEFFERNAN	DAL	DENIAL OF FLOATING HOLIDAY	DEADLOCKED
SWA-6391	LYNDON HEFFERNAN	DAL	DENIL OF FLOATING HOLIDAY	DEADLOCKED
SWA-6392	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6393	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6394	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6395	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6396	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6397	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6398	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6399	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6400	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6401	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6402	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6403	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6404	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6405	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6406	GROUP QC	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6407	MIKE HAMBLIN	ATL	REINSTATEMENT OF VACATION DAYS <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6408	STEVE LEWIS	HOU	DENIAL OF CANCELATION REQUEST FOR VACATION	DEADLOCKED
SWA-6409	GROUP	ALL	GROUP / AMT / 14084 REV: 04 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE A/C 215, 7746, 209, 551	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6410	GROUP	ALL	GROUP / AMT / J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR A/C 215, 564, 7746, 209	DEADLOCKED
SWA-6411	GROUP	ALL	GROUP / AMT / 33364 REV: POS: AD DRIVEN SI# 12042-53 STEP 2.A. BS 540 LOWER BULKHEAD CHORDS LEFT SIDE BETWEEN STRINGER 22L AND 23L HAS CRACK INDICATION IN UPPER CHORD LOWER AFT FASTENER HOLE A/C 215	DEADLOCKED
SWA-6412	GROUP	ALL	GROUP / AMT / 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 7746 <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6413	GROUP	ALL	GROUP / AMT / 753-10-07 REV: POS: DVI - INTERNAL AND EXTERNAL RADOME AND ADAPTER RING - ROW 44 WI-FI INSTALLATION A/C 7746 <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6414	GROUP	ALL	GROUP / AMT / J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES A/C 7746	DEADLOCKED
SWA-6415	GROUP	ALL	GROUP / AMT / 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS A/C 209	DEADLOCKED
SWA-6416	GROUP	ALL	GROUP / AMT / 32716 REV: POS: STA 540R CORD TWO FASTNERS BELOW STR 22R CRACKED FWD/ AFT BETWEEN 2 FASTNERS. ALSO CONTINUES TROUGH THEAFT FASTNER A/C 209	DEADLOCKED
SWA-6417	GROUP	ALL	GROUP / AMT / 32718 REV: POS: HFEC CRACK INDICATION IN FASTENER HOLE, IN AFT ROW 2ND HOLE FROM TOP, AT STA.540, BELOW S-22L OF REQUIRED INSPECTION AREA OF ROUTINE CARD SI 12042-53,STEP 2A.1 A/C 209	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6418	GROUP	ALL	GROUP / AMT / 753-10-07 REV: POS: DVI - INTERNAL AND EXTERNAL RADOME AND ADAPTER RING - ROW 44 WI-FI INSTALLATION A/C 551 <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6419	GROUP	ALL	GROUP / AMT / D234693 EVIDENCE OF LIGHTNING STRIKE DAMAGE RIVET AT STA997 AND S4R A/C 551	WITHDRAWN
SWA-6420	GROUP	ALL	GROUP / AMT / D234709 EVIDENCE OF LIGHTNING STRIKE DAMAGE RIVET AT STA 808 AND S2R A/C 551	WITHDRAWN
SWA-6421	GROUP	ALL	GROUP / AMT / D234711 EVIDENCE OF LIGHTNING STRIKE DAMAGED RIVET AT STA 832 AND S2R A/C 551	WITHDRAWN
SWA-6422	TOM NOLAN	HOU	TRAINING NON COMPLIANCE LOW CONFLICTS WITH MPM	DEADLOCKED
SWA-6423	SHANE FLACHMAN	HOU	LOW FOR READ AND SIGN <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6424	ISAAC GILKIE	MDW	REIMBURSEMENT FOR OUT OF POCKET MEAL EXPENSES FOR TRAINING <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6425	BENJAMIN WAGNER	MDW	REIMBURSEMENT FOR OUT OF POCKET MEAL EXPENSES FOR TRAINING <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6426	TROY CONNOR	MDW	REIMBURSEMENT FOR OUT OF POCKET MEAL EXPENSES FOR TRAINING <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6427	SCOTT ANDREZJWSKI	DAL	CROSS UTILIZATION VIOLATION	DEADLOCKED
SWA-6428	GROUP ALL	DAL	OUTSOURCING VIOLATION – SLIDES <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6429	GROUP ALL	DAL	OUTSOURCING VIOLATION – GEAR DOORS	WITHDRAWN



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6430	GROUP PMX	DAL	OUTSOURCING VIOLATION – JACKS	DEADLOCKED
SWA-6431	GROUP PMX	DAL	OUTSOURCING VIOLATION – O3 TOOL	DEADLOCKED
SWA-6432	GROUP PMX	DAL	OUTSOURCING VIOLATION -BRAKE DOLLY	DEADLOCKED
SWA-6433	GROUP PMX	DAL	OUTSOURCING VIOLATION – JACKS	DEADLOCKED
SWA-6434	RICHARD HAMMACK	DAL	LEAD DUTIES <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6435	GROUP ALL	DAL	OUTSOURCING VIOLATION – SLIDES <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6436	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV TASK 810-PRD-03-01 SVC - PREPERATION FOR ACTIVE STORAGE ON ALL MAX A/C IN VCV <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6437	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV TASK 810-PRD-04-01 SVC - SERVICE AND PROTECTION ON A 7 DAY (1 WEEK) CYCLE A/C 8702, 8706, 8710, 8714, 8715, 8717, 8719, 8727, 8732, 8735	DEADLOCKED
SWA-6438	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV FUEL SUMP DRAINING WORK SCOPES C/W DAILY PER M/M 12-11- 00-680-801 TRACKED ON SAM 326 A/C 8702, 8706, 8710, 8714, 8715, 8717, 8719, 8727, 8732, 8735	DEADLOCKED
SWA-6439	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV TASK INSP-72EA-06674 LEAP - ENGINE ONE TIME ON-WING BSI OF HPT AND LPT SECTION BOTH ENGINES ON A/C 8706, 8711 AND ENGINE S/N 602141 ON A/C 8716	DEADLOCKED





<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6440	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV TASK INSP-72EA-06674 LEAP - ENGINE ONE TIME ON-WING BSI OF HPT AND LPT SECTION A/C 8707 S/N 602175, A/C 8713 S/N 602169, A/C 8715 S/N 602154	DEADLOCKED
SWA-6441	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV TASK 810-PRD-04-01 SVC - SERVICE AND PROTECTION ON A 7 DAY (1 WEEK) CYCLE A/C 8709, 8720, 8722, 8729	DEADLOCKED
SWA-6442	GROUP	ALL	GROUP ALL / AMT / MAX IN VCV FUEL SUMP DRAINING WORK SCOPES C/W DAILY PER M/M 12-11-00-680-801 TRACKED ON SAM 326 A/C 8705, 8709, 8720, 8722, 8729	DEADLOCKED
SWA-6443	GROUP	ALL	GROUP ALL / AMT / DOWNLINE ROADTRIP OUTSOURCING A/C N415 <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6444	LOREN HOFFMAN	HOU	LEAD PAY NOT PAID AND LEAD SPOT NOT POSTED <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6445	GROUP	ALL	GROUP ALL / AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 937, 282 <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6446	GROUP	ALL	GROUP ALL / AMT / E14084 04 MOD TYPE: E NBR: 14084 REV: 04 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE A/C 937, 212, 282, 7815	DEADLOCKED
SWA-6447	GROUP	ALL	GROUP ALL / AMT / D164887 REF NON-ROUTINE D164887. DENT ON RIGHT SIDE OF FUSELAGE STA 910R, S- 18R +4 MOD A/C 937	WITHDRAWN
SWA-6448	GROUP	ALL	GROUP ALL / AMT / 0687677 RT STABILIZER HAS A DENT ABOUT ONE FOOT FROM THE FUSELAGE A/C 937 <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6449	GROUP	ALL	GROUP ALL / AMT / J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR A/C 937, 212, 282, 7815	DEADLOCKED
SWA-6450	GROUP	ALL	GROUP ALL / AMT / J752-200-00-03 HEALTH CHECK - DOOR WARNING SYSTEM - SENSORS/SWITCHES A/C 937, 212	DEADLOCKED
SWA-6451	GROUP	ALL	GROUP ALL / AMT / 8753-10-07 MOD TYPE: 8 NBR: 753-10-07 REV: POS: DVI - INTERNAL AND EXTERNAL RADOME AND ADAPTER RING - ROW 44 WI-FI INSTALLATION A/C 282, 7815 <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD
SWA-6452	GROUP	ALL	GROUP ALL / AMT / 633470 MOD TYPE: 6 NBR: 33470 REV: POS: FOUND A CRACK INDICATION ON THE FUSELAGE SKIN WHILE PERFORMING AN HFEC INSPECTION AROUND THE 8 FASTENERS COMMON TO THE 540 BULKHEAD CHORD BETWEEN STRINGERS 22L AND 23L. A/C 282	DEADLOCKED
SWA-6453	GROUP	ALL	GROUP ALL / AMT / J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES A/C 282	DEADLOCKED
SWA-6454	GROUP	ALL	GROUP ALL / AMT / 8727-61-02 MOD TYPE: 8 NBR: 727-61-02 REV: POS: FNC - SPOILER RATIO CHANGER NO-BACK ASSEMBLY A/C 289	DEADLOCKED
SWA-6455	GROUP	ALL	GROUP ALL / AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 289, 435, 734, 735, 957 <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6456	GROUP	ALL	GROUP ALL / AMT / 8753-10-07 MOD TYPE: 8 NBR: 753-10-07 REV: POS: DVI - INTERNAL AND EXTERNAL RADOME AND ADAPTER RING - ROW 44 WI-FI INSTALLATION A/C 289 <i>CURRENTLY ON COMPANY HOLD</i>	COMPANY HOLD



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6457	GROUP	ALL	GROUP ALL / AMT / E14084 04 MOD TYPE: E NBR: 14084 REV: 04 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE A/C 289, 435, 438, 734, 735, 957, 7828, 7823	DEADLOCKED
SWA-6458	GROUP	ALL	GROUP ALL / AMT / J727-009-00-01 REP - LEFT AND RIGHT WING AILERON AND SPOILER CABLES A/C 289	DEADLOCKED
SWA-6459	GROUP	ALL	GROUP ALL / AMT / J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR A/C 289, 435, 438, 734, 735, 7828, 7823	DEADLOCKED
SWA-6460	GROUP	ALL	GROUP ALL / AMT / 14090 INSPECTION OF UPPER FUSELAGE SKIN UNDER DORSAL FIN A/C 289, 7828	DEADLOCKED
SWA-6461	GROUP	ALL	GROUP ALL / AMT / E08762 02 MOD TYPE: E NBR: 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS A/C 435, 7828	DEADLOCKED
SWA-6462	GROUP	ALL	GROUP ALL / AMT / 633068 MOD TYPE: 6 NBR: 33068 REV: POS: CRACK AROUND FASTENER HOLE ON SKIN COMMON TO LOWER BULKHEAD CHORD BS540 S22L A/C 435	DEADLOCKED
SWA-6463	GROUP	ALL	GROUP ALL / AMT / 633501 MOD TYPE: 6 NBR: 33501 REV: POS: FUSELAGE SKIN CRACKED AT FASTENER HOLE COMMON TO THEBS540 BLKHD CHORD BETWEEN STR22R-23R A/C 438	DEADLOCKED
SWA-6464	GROUP	ALL	GROUP ALL / AMT / 633503 MOD TYPE: 6 NBR: 33503 REV: POS: FUSELAGE SKIN CRACKED AT FASTENER HOLES 2(EA) COMMON TO THE BS540 BLKHD CHORD BETWEEN STR22L-23L A/C 438	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6465	GROUP	ALL	GROUP ALL / AMT / 633971 MOD TYPE: 6 NBR: 33971 REV: POS: INBOUND DMI - LEFT SIDE STA 540. TWO CRACKS FOUND PROPAGATING AT TWO FASTENER HOLES. REPAIRED SKIN PEREA 1-753-25551 REPLACE THE REPAIR TO A CATEGORY A ORB REPAIR WITHIN 24 MONTHS A/C 734	DEADLOCKED
SWA-6466	GROUP	ALL	GROUP ALL / AMT / 633973 MOD TYPE: 6 NBR: 33973 REV: POS: INBOUND DMI- RIGHT SIDE STA 540. TWO CRACKS FOUND AT TWO FASTENER HOLES. REPAIRED SKIN PER EA 1-753-25552 REPLACE THE REPAIR TO A CATEGORY A OR B REPAIR WITHIN 24 MONTHS A/C 734	DEADLOCKED
SWA-6467	GROUP	ALL	GROUP ALL / AMT / 8757-606-000-01 MOD TYPE: 8 NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL A/C 734, 735	DEADLOCKED
SWA-6468	GROUP	ALL	GROUP ALL / AMT / 8757-606-000-02 MOD TYPE: 8 NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL A/C 734, 735	DEADLOCKED
SWA-6469	GROUP	ALL	GROUP ALL / AMT / 8757-607-100-01 MOD TYPE: 8 NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL A/C 734, 735	DEADLOCKED
SWA-6470	GROUP	ALL	GROUP ALL / AMT / 8757-607-100-02 MOD TYPE: 8 NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL A/C 734, 735	DEADLOCKED
SWA-6471	GROUP	ALL	GROUP ALL / AMT / 8757-613-000-01 MOD TYPE: 8 NBR: 757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS A/C 734, 735	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6472	GROUP	ALL	GROUP ALL / AMT / 8757-613-000-02 MOD TYPE: 8 NBR: 757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS A/C 734, 735	DEADLOCKED
SWA-6473	GROUP	ALL	GROUP ALL / AMT / 8757-619-101-01 MOD TYPE: 8 NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS A/C 734, 735	DEADLOCKED
SWA-6474	GROUP	ALL	GROUP ALL / AMT / 8757-619-101-02 MOD TYPE: 8 NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS A/C 734, 735	DEADLOCKED
SWA-6475	GROUP	ALL	GROUP ALL / AMT / 8757-620-101-01 MOD TYPE: 8 NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER A/C 734	DEADLOCKED
SWA-6476	GROUP	ALL	GROUP ALL / AMT / 8757-620-101-02 MOD TYPE: 8 NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER A/C 734	DEADLOCKED
SWA-6477	GROUP	ALL	GROUP ALL / AMT / 8757-622-000-01 MOD TYPE: 8 NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED
SWA-6478	GROUP	ALL	GROUP ALL / AMT / 8757-622-000-02 MOD TYPE: 8 NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED
SWA-6479	GROUP	ALL	GROUP ALL / AMT / 8757-632-010-01 MOD TYPE: 8 NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED
SWA-6480	GROUP	ALL	GROUP ALL / AMT / 8757-632-010-02 MOD TYPE: 8 NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6481	GROUP	ALL	GROUP ALL / AMT / 8757-638-000-01 MOD TYPE: 8 NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED
SWA-6482	GROUP	ALL	GROUP ALL / AMT / 8757-638-000-02 MOD TYPE: 8 NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 734, 735	DEADLOCKED
SWA-6483	GROUP	ALL	GROUP ALL / AMT / 8757-643-010-01 MOD TYPE: 8 NBR: 757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS A/C 734, 735	DEADLOCKED
SWA-6484	GROUP	ALL	GROUP ALL / AMT / 8757-643-010-02 MOD TYPE: 8 NBR: 757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS A/C 734, 735	DEADLOCKED
SWA-6485	GROUP	ALL	GROUP ALL / AMT / 8757-644-000-01 MOD TYPE: 8 NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) A/C 734, 735	DEADLOCKED
SWA-6486	GROUP	ALL	GROUP ALL / AMT / 8757-644-000-02 MOD TYPE: 8 NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) A/C 734, 735	DEADLOCKED
SWA-6487	GROUP	ALL	GROUP ALL / AMT / 8757-644-001-01 MOD TYPE: 8 NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) A/C 734, 735	DEADLOCKED
SWA-6488	GROUP	ALL	GROUP ALL / AMT / 8757-644-001-02 MOD TYPE: 8 NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) A/C 734, 735	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6489	GROUP	ALL	GROUP ALL / AMT / 8757-645-000-01 MOD TYPE: 8 NBR: 757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL A/C 734, 735	DEADLOCKED
SWA-6490	GROUP	ALL	GROUP ALL / AMT / 8757-645-000-02 MOD TYPE: 8 NBR: 757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL A/C 734, 735	DEADLOCKED
SWA-6491	GROUP	ALL	GROUP ALL / AMT / 8757-650-000-01 MOD TYPE: 8 NBR: 757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1) A/C 734, 735	DEADLOCKED
SWA-6492	GROUP	ALL	GROUP ALL / AMT / 8757-650-000-02 MOD TYPE: 8 NBR: 757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1) A/C 734, 735	DEADLOCKED
SWA-6493	GROUP	ALL	GROUP ALL / AMT / 8757-699-000-01 MOD TYPE: 8 NBR: 757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAST ENER ATTACHMENTS A/C 734, 735	DEADLOCKED
SWA-6494	GROUP	ALL	GROUP ALL / AMT / 8757-699-000-02 MOD TYPE: 8 NBR: 757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAS TENER ATTACHMENTS A/C 734, 735	DEADLOCKED
SWA-6495	GROUP	ALL	GROUP ALL / AMT / 8757-701-000-01 MOD TYPE: 8 NBR: 757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27 A/C 734, 735	DEADLOCKED
SWA-6496	GROUP	ALL	GROUP ALL / AMT / 8757-701-000-02 MOD TYPE: 8 NBR: 757-701-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING TENSION FITTINGS AT RIB 27 A/C 734, 735	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6497	GROUP	ALL	GROUP ALL / AMT / 8757-702-000-01 MOD TYPE: 8 NBR: 757-702-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACH MENTS (DIRECTION 1) A/C 734, 735	DEADLOCKED
SWA-6498	GROUP	ALL	GROUP ALL / AMT / 8757-702-000-02 MOD TYPE: 8 NBR: 757-702-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTAC HMENTS (DIRECTION 1) A/C 734, 735	DEADLOCKED
SWA-6499	GROUP	ALL	GROUP ALL / AMT / 8757-702-001-01 MOD TYPE: 8 NBR: 757-702-001-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENER ATTACHMENTS A/C 735	DEADLOCKED
SWA-6500	GROUP	ALL	GROUP ALL / AMT / 8757-702-001-02 MOD TYPE: 8 NBR: 757-702-001-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT OUTBOARD WING RIB 27 UPPER FLANGE AT SKIN FASTENE R ATTACHMENTS A/C 735	DEADLOCKED
SWA-6501	GROUP	ALL	GROUP ALL / AMT / 8757-703-000-01 MOD TYPE: 8 NBR: 757-703-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING RIB 27, FRONT AND REAR SPAR TENSION FITTINGS A/C 734, 735	DEADLOCKED
SWA-6502	GROUP	ALL	GROUP ALL / AMT / 8757-703-000-02 MOD TYPE: 8 NBR: 757-703-000-02 REV: POS: SDI (HFEC) - INTERNAL - RIGHT WING RIB 27, FRONT ANDREAR SPAR TENSION FITTINGS A/C 734, 735	DEADLOCKED
SWA-6503	GROUP	ALL	GROUP ALL / AMT / 61539 MOD TYPE: 6 NBR: 1539 REV: POS: OVERWING AREA, CABIN CENTER SECTION BENEATH FLOOR, STA 663 BULKHEAD, LBL 35 HAS A CRACK A/C 735	WITHDRAWN





<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6504	GROUP	ALL	GROUP ALL / AMT / 61540 MOD TYPE: 6 NBR: 1540 REV: POS: OVERWING AREA, CABIN CENTER SECTION BENEATH FLOOR, STA 663 BULKHEAD, LBL 43 HAS A CRACK A/C 735	WITHDRAWN
SWA-6505	GROUP	ALL	GROUP ALL / AMT / (21 DAY REPEAT) TASK; 810-PRD-04-01 SVC - SERVICE AND PROTECTION ON 7 DAY (1 WEEK) CYCLE A/C 8709, 8720, 8729	DEADLOCKED
SWA-6506	GROUP	ALL	GROUP ALL / AMT / MAX ELEVATOR SWITCH IDENTIFICATION - VCV TASK 2731-I-14477 ELEVATOR JAM LANDING ASSIST SWITCH IDENTIFICATION A/C 8701 THRU A/C 8735 EXCEPT 8712	DEADLOCKED
SWA-6507	GROUP	ALL	GROUP ALL / AMT / (28 DAY REPEAT) TASK 810-PRD-06-01 SVC - SERVICE AND PROTECTION ON 30 DAY (1 MONTH) CYCLE A/C 8705, 8709, 8720, 8722, 8729	DEADLOCKED
SWA-6508	DONNA JOHNSON	DAL	UNJUST PUNISHMENT	WITHDRAW W/O PREJUDICE
SWA-6509	GROUP PMX	DAL	OUTSOURCING VIOLATION – JACKS	DEADLOCKED
SWA-6510	CLARKE DICKERSON	DAL	DOWNLINE VIOLATION – AC455	SETTLED PRIOR
SWA-6511	GERALD DELGADO	DAL	DOWNLINE VIOLATION – AC455	SETTLED PRIOR
SWA-6512	GROUP	ALL	GROUP ALL / AMT / E08762 02 MOD TYPE: E NBR: 08762 REV: 02 POS: ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS A/C 436, 434, 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6513	GROUP	ALL	GROUP ALL / AMT / E14084 04 MOD TYPE: E NBR: 14084 REV: 04 POS: LEFT AND RIGHT WING LEADING EDGE UPPER SKIN PANEL FASTENER CHANGE A/C 436, 731, 956, 934, 280, 936, 219, 434, 748, 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6514	GROUP	ALL	GROUP ALL / AMT / 633203 MOD TYPE: 6 NBR: 33203 REV: POS: BS 540 L/H BULKHEAD CHORD BELOW S- 22L, SECOND FASTNER DOWN ON AFT SIDE CRACK INDICATION PER NDT MANUAL PART 6 51-00-00 PROCEDURE 23 A/C 436 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6515	GROUP	ALL	GROUP ALL / AMT / J732-305-00-01 REP - STEERING SYSTEM CABLES FOR THE NOSE GEAR A/C 436, 956, 748, 934, 280, 936, 219, 434, 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6516	GROUP	ALL	GROUP ALL / AMT / 8728-22-21 MOD TYPE: 8 NBR: 728-22-21 REV: POS: DVI - OUT-OF-TANK WIRE BUNDLE (INSTALLED ON FUEL TANK) A/C 731, 934, 936, 219, 434, 280 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6517	GROUP	ALL	GROUP ALL / AMT / 8772-21-20 MOD TYPE: 8 NBR: 772-21-20 REV: POS: 1 CFM56-7 FAN BLADE, DISK AND DISK DOVETAIL SLOT CLEANING, INSPECTION AND RELUBRICATION COMPONENT DISCREPANCY RECORD: 0720035 893441 A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6518	GROUP	ALL	GROUP ALL / AMT / 8772-21-21 MOD TYPE: 8 NBR: 772-21-21 REV: POS: 1 SDI - ULTRA SONIC (UT) INSPECTION OF FAN BLADE DOVETAILS (COMPLETE SET) COMPONENT DISCREPANCY RECORD: 0720035 893441 A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-6519	GROUP	ALL	<p>GROUP ALL / AMT / I12246 02 MOD TYPE: I NBR: 12246 REV: 02 POS: HEAT EXCHANGER PLENUM &amp; DIFFUSER DETAILED VISUAL INSPECTION A/C 731, 956</p> <p><b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6520	GROUP	ALL	<p>GROUP ALL / AMT / 61651 MOD TYPE: 6 NBR: 1651 REV: POS: FWD SIDE OF PRESSURE DECK IN CENTER CABIN @ BS 663 LBL 43 HAS 2" CRACK IN WEB</p> <p>61652 MOD TYPE: 6 NBR: 1652 REV: POS: FWD SIDE OF PRESSURE DECK IN CENTER CABIN @ BS 663 LBL 43 HAS 2" CRACK IN WEB</p> <p>A/C 731</p> <p><b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6521	GROUP	ALL	<p>GROUP ALL / AMT / 633722 MOD TYPE: 6 NBR: 33722 REV: POS: EXISTING REPAIR LOCATED ON LOWER BULKHEAD CHORD BS 540 BELOW STR 22 L EXTERNAL FUSELAGE .</p> <p>633724 MOD TYPE: 6 NBR: 33724 REV: POS: EXISTING REPAIR ON LOWER BULK HEAD CHORD LOCATED AT BS 540 BELOW STR 22 R EXTERIOR FUSELAGE.</p> <p>A/C 731</p> <p><b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6522	GROUP	ALL	<p>GROUP ALL / AMT / 8757-606-000-01 MOD TYPE: 8 NBR: 757-606-000-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL A/C 731, 748</p> <p><b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6523	GROUP	ALL	<p>GROUP ALL / AMT / 8757-606-000-02 MOD TYPE: 8 NBR: 757-606-000-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL A/C 731, 748</p> <p><b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6524	GROUP	ALL	GROUP ALL / AMT / 8757-606-001-01 MOD TYPE: 8 NBR: 757-606-001-01 REV: POS: SDI - (HFEC) - INTERNAL - LEFT WING CENTER SECTION LOWER PANEL (DIRECTION 1) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6525	GROUP	ALL	GROUP ALL / AMT / 8757-607-100-01 MOD TYPE: 8 NBR: 757-607-100-01 REV: POS: SDI - WING CENTER SECTION LEFT LOWER PANEL A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6526	GROUP	ALL	GROUP ALL / AMT / 8757-607-100-02 MOD TYPE: 8 NBR: 757-607-100-02 REV: POS: SDI - WING CENTER SECTION RIGHT LOWER PANEL A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6527	GROUP	ALL	GROUP ALL / AMT / 8757-613-000-01 MOD TYPE: 8 NBR: 757-613-000-01 REV: POS: SDI (LFEC) - INTERNAL - LEFT LOWER WING PANEL STRINGERS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6528	GROUP	ALL	GROUP ALL / AMT / 8757-613-000-02 MOD TYPE: 8 NBR: 757-613-000-02 REV: POS: SDI (LFEC) - INTERNAL - RIGHT LOWER WING PANEL STRINGERS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6529	GROUP	ALL	GROUP ALL / AMT / 8757-619-101-01 MOD TYPE: 8 NBR: 757-619-101-01 REV: POS: SDI (LFEC) - EXTERNAL - LEFT LOWER WING PANEL, SPLICE STRINGERS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6530	GROUP	ALL	GROUP ALL / AMT / 8757-619-101-02 MOD TYPE: 8 NBR: 757-619-101-02 REV: POS: SDI (LFEC) - EXTERNAL - RIGHT LOWER WING PANEL, SPLICE STRINGERS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6531	GROUP	ALL	GROUP ALL / AMT / 8757-620-101-01 MOD TYPE: 8 NBR: 757-620-101-01 REV: POS: SDI - EXTERNAL - LEFT WING LOWER PANEL, SPLICE STRINGER A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6532	GROUP	ALL	GROUP ALL / AMT / 8757-620-101-02 MOD TYPE: 8 NBR: 757-620-101-02 REV: POS: SDI - EXTERNAL - RIGHT WING LOWER PANEL, SPLICE STRINGER A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6533	GROUP	ALL	GROUP ALL / AMT / 8757-622-000-01 MOD TYPE: 8 NBR: 757-622-000-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6534	GROUP	ALL	GROUP ALL / AMT / 8757-622-000-02 MOD TYPE: 8 NBR: 757-622-000-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6535	GROUP	ALL	GROUP ALL / AMT / 8757-632-010-01 MOD TYPE: 8 NBR: 757-632-010-01 REV: POS: SDI - EXTERNAL - LEFT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6536	GROUP	ALL	GROUP ALL / AMT / 8757-632-010-02 MOD TYPE: 8 NBR: 757-632-010-02 REV: POS: SDI - EXTERNAL - RIGHT FRONT SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6537	GROUP	ALL	GROUP ALL / AMT / 8757-638-000-01 MOD TYPE: 8 NBR: 757-638-000-01 REV: POS: SDI - EXTERNAL - LEFT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6538	GROUP	ALL	GROUP ALL / AMT / 8757-638-000-02 MOD TYPE: 8 NBR: 757-638-000-02 REV: POS: SDI - EXTERNAL - RIGHT REAR SPAR LOWER CHORD (SKIN FLANGE INSPECTIONS) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6539	GROUP	ALL	GROUP ALL / AMT / 8757-643-010-01 MOD TYPE: 8 NBR: 757-643-010-01 REV: POS: SDI (HFEC) - EXTERNAL - LEFT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6540	GROUP	ALL	GROUP ALL / AMT / 8757-643-010-02 MOD TYPE: 8 NBR: 757-643-010-02 REV: POS: SDI (HFEC) - EXTERNAL - RIGHT LOWER WING PANEL SKIN AT SHEAR TIED RIB ATTACHMENTS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6541	GROUP	ALL	GROUP ALL / AMT / 8757-644-000-01 MOD TYPE: 8 NBR: 757-644-000-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) A/V 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6542	GROUP	ALL	GROUP ALL / AMT / 8757-644-000-02 MOD TYPE: 8 NBR: 757-644-000-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1 AND DIRECTION 2) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6543	GROUP	ALL	GROUP ALL / AMT / 8757-644-001-01 MOD TYPE: 8 NBR: 757-644-001-01 REV: POS: SDI - LEFT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6544	GROUP	ALL	GROUP ALL / AMT / 8757-644-001-02 MOD TYPE: 8 NBR: 757-644-001-02 REV: POS: SDI - RIGHT LOWER WING PANEL UNDER FLAP TRACK FITTINGS (DIRECTION 1) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6545	GROUP	ALL	GROUP ALL / AMT / 8757-645-000-01 MOD TYPE: 8 NBR: 757-645-000-01 REV: POS: DVI - EXTERNAL - LEFT UPPER WING PANEL A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6546	GROUP	ALL	GROUP ALL / AMT / 8757-645-000-02 MOD TYPE: 8 NBR: 757-645-000-02 REV: POS: DVI - EXTERNAL - RIGHT UPPER WING PANEL A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6547	GROUP	ALL	GROUP ALL / AMT / 8757-650-000-01 MOD TYPE: 8 NBR: 757-650-000-01 REV: POS: DVI - INTERNAL - LEFT OUTBOARD WING REAR SPAR WEB (DIRECTION 1) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6548	GROUP	ALL	GROUP ALL / AMT / 8757-650-000-02 MOD TYPE: 8 NBR: 757-650-000-02 REV: POS: DVI - INTERNAL - RIGHT OUTBOARD WING REAR SPAR WEB (DIRECTION 1) A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6549	GROUP	ALL	GROUP ALL / AMT / 8757-699-000-01 MOD TYPE: 8 NBR: 757-699-000-01 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - LEFT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAST ENER ATTACHMENTS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6550	GROUP	ALL	GROUP ALL / AMT / 8757-699-000-02 MOD TYPE: 8 NBR: 757-699-000-02 REV: POS: SDI (HFEC)/(LFEC) - INTERNAL - RIGHT WING RIB 27 - RIB LOWER FLANGE AT SKIN FAS TENER ATTACHMENTS A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6551	GROUP	ALL	GROUP ALL / AMT / 8757-701-000-01 MOD TYPE: 8 NBR: 757-701-000-01 REV: POS: SDI (HFEC) - INTERNAL - LEFT WING TENSION FITTINGS AT RIB 27 A/C 731, 748 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR



CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-6552	GROUP	ALL	<p>GROUP ALL / AMT / 8757-701-000-02            MOD TYPE: 8 NBR: 757-701-000-02            REV: POS: SDI (HFEC) - INTERNAL -            RIGHT WING TENSION FITTINGS AT            RIB 27 A/C 731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6553	GROUP	ALL	<p>GROUP ALL / AMT / 8757-702-000-01            MOD TYPE: 8 NBR: 757-702-000-01            REV: POS: DVI - INTERNAL - LEFT            OUTBOARD WING RIB 27 UPPER            FLANGE AT SKIN FASTENER            ATTACH MENTS (DIRECTION 1) A/C            731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6554	GROUP	ALL	<p>GROUP ALL / AMT / 8757-702-000-02            MOD TYPE: 8 NBR: 757-702-000-02            REV: POS: DVI - INTERNAL - RIGHT            OUTBOARD WING RIB 27 UPPER            FLANGE AT SKIN FASTENER ATTAC            HMENTS (DIRECTION 1) A/C 731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6555	GROUP	ALL	<p>GROUP ALL / AMT / 8757-702-001-01            MOD TYPE: 8 NBR: 757-702-001-01            REV: POS: SDI (LFEC) - EXTERNAL -            LEFT OUTBOARD WING RIB 27            UPPER FLANGE AT SKIN FASTENER            ATTACHMENTS A/C 731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6556	GROUP	ALL	<p>GROUP ALL / AMT / 8757-702-001-02            MOD TYPE: 8 NBR: 757-702-001-02            REV: POS: SDI (LFEC) - EXTERNAL -            RIGHT OUTBOARD WING RIB 27            UPPER FLANGE AT SKIN FASTENE R            ATTACHMENTS A/C 731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6557	GROUP	ALL	<p><b>GROUP ALL / AMT / 8757-703-000-01</b>  <b>MOD TYPE: 8 NBR: 757-703-000-01</b>  <b>REV: POS: SDI (HFEC) - INTERNAL -</b>  <b>LEFT WING RIB 27, FRONT AND</b>  <b>REAR SPAR TENSION FITTINGS A/C</b>  <b>731, 748</b>  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR





CASE #	GRIEVANT	STA	NATURE	DECISION
SWA-6558	GROUP	ALL	<p>GROUP ALL / AMT / 8757-703-000-02            MOD TYPE: 8 NBR: 757-703-000-02            REV: POS: SDI (HFEC) - INTERNAL -            RIGHT WING RIB 27, FRONT            ANDREAR SPAR TENSION FITTINGS            A/C 731, 748  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6559	GROUP	ALL	<p>GROUP ALL / AMT / J752-200-00-03            HEALTH CHECK - DOOR WARNING            SYSTEM - SENSORS/SWITCHES A/C            934, 936, 219, 8612, 8613  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6560	GROUP	ALL	<p>GROUP ALL / AMT / 8727-61-02 MOD            TYPE: 8 NBR: 727-61-02 REV: POS: FNC            - SPOILER RATIO CHANGER NO-            BACK ASSEMBLY A/C 280  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6561	GROUP	ALL	<p>GROUP ALL / AMT / J727-009-00-01            REP - LEFT AND RIGHT WING            AILERON AND SPOILER CABLES A/C            280  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6562	GROUP	ALL	<p>GROUP ALL / AMT / 632470 MOD            TYPE: 6 NBR: 32470 REV: POS: CRACK            INDICATION FOUND AROUND HOLE            OF FUSELAGE SKIN LOCATED AT BS            540 AND 2" BELOW S- 22L AFT            POSITION AT LOWER BULKHEAD.            632472 MOD TYPE: 6 NBR: 32472 REV:            POS: CRACK INDICATION FOUND            AROUND HOLE OF FUSELAGE SKIN            LOCATED AT BS 540 AND 2" BELOW            S-22R AFT POSITION AT LOWER            BULKHEAD.            A/C 434  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR
SWA-6563	GROUP	ALL	<p>GROUP ALL / AMT / 8753-10-07 MOD            TYPE: 8 NBR: 753-10-07 REV: POS: DVI            - INTERNAL AND EXTERNAL            RADOME AND ADAPTER RING - ROW            44 WI-FI INSTALLATION A/C 280, 8612,            8613  <b>OUT OF TIME FRAMES</b></p>	SETTLED PRIOR



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
SWA-6564	GROUP	ALL	GROUP ALL / AMT / INSP-21EO-03374 HEAT EXCHANGER PLENUM & DIFFUSER DETAILED VISUAL INSPECTION A/C 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6565	GROUP	ALL	GROUP ALL / AMT / INSP-24EO-10189 ELECTRICAL POWER-GENERAL-CORROSION INSPECTION AND PROTECTION OF CONNECTORS IN A/C 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6566	GROUP	ALL	GROUP ALL / AMT / MOD-25EO-01310 737-800 OWWE WINDOW SHADE MODIFICATION A/C 8612, 8613 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6567	GROUP	ALL	GROUP ALL / AMT / REPAIR-55EA-05740 COMPONENT - SWA - REPAIR - R/H HORIZONTAL STABILIZER L/E SKIN DENT LOCATED BETWEEN STA 294.55 - 298.05 PERMANENT REPAIR REQ'D PER SRM 55-10-01 (PN 186A1001-24, SN 8612-RH, INSTALLED ON 8612) A/C 8612 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6568	GROUP	ALL	GROUP ALL / AMT / REPAIR-55EA-06172 SWA-OTHER-RH HORIZONTAL STABILIZER LEADING EDGE SKIN DENT-PERMANENT REPAIR A/C 8612 <b>OUT OF TIME FRAMES</b>	SETTLED PRIOR
SWA-6570	JASON GILBRECH	DAL	OUTSOURCING VIOLATION – HORZ STAB LE <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6571	JASON GILBRECH	DAL	OUTSOURCING VIOLATION – 700 TR <i>CURRENTLY ON UNION HOLD</i>	UNION HOLD
SWA-6572	GROUP PMX	DAL	OUTSOURCING VIOLATION – 50 TON JACK	DEADLOCKED
SWA-6573	GROUP PMX	DAL	OUTSOURCING VIOLATION – WHEEL/BRAKE DOLLY	DEADLOCKED



<b>CASE #</b>	<b>GRIEVANT</b>	<b>STA</b>	<b>NATURE</b>	<b>DECISION</b>
<b>SWA-6574</b>	<b>GROUP PMX</b>	<b>DAL</b>	<b>OUTSOURCING VIOLATION – 10 TON NOSE JACK</b>	<b>DEADLOCKED</b>
<b>SWA-6575</b>	<b>GROUP PMX</b>	<b>DAL</b>	<b>OUTSOURCING VIOLATION – 10 TON NOSE JACK</b>	<b>DEADLOCKED</b>